

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS/ICS21003417/EQF3N2  
**Date:** 21/06/2021

**REFERENCE**

Handling Insurer: ECICS Limited Policy No: MPC20A00052800  
**Claimant Vehicle No :** SJZ1186K **Insured Vehicle No :** SDV9955Y  
 Date of Loss: 21/02/2021 Nature of Claim: TP Claim No: DMPC2100065H

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SJZ1186K**  
 Make & Model: BMW 520i, 2.0 (A) Engine No: F957K298B48B20A  
 Reg. Date: 28/09/2020 (Man. Year: 2019) Chassis No: WBAJR12070CD80448  
 Colour: Black Odometer: 23927 km  
 Engine Capacity: 1998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18  
 Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm  
 Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,820.00	2,394.45	425.55	15.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,544.00	3,415.00	1,129.00	24.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,364.00</b>	<b>5,809.45</b>	<b>1,554.55</b>	<b>21.11</b>
<b>+ GST 7.00/7.00% (S\$)</b>	515.48	406.66	108.82	21.11
<b>Nett Amount (S\$)</b>	<b>7,879.48</b>	<b>6,216.11</b>	<b>1,663.37</b>	<b>21.11</b>

**INSPECTION**

Date of Assignment: 16/03/2021  
 Date Inspected: 16/03/2021 Inspected At: Performance Motors Limited (Alexandra)  
 303 Alexandra Road, Sime Darby Performance Centre  
 Singapore 159941  
 Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

NOTE: THE DIFFERENT \$100.00 IS DUE TO WORKSHOP TYPO ERROR IN FINALISATION.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2021)
<b>Parts:</b>	143	BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	<b>LKK Auto Consultants Pte Ltd/SJZ1186K/21/06/2021 16:50</b>	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR ALUMINIUM	Dented	1,881.90 FS	*1,881.90 FS
2	1		*(S/L) DOOR WEATHERSTRIP	Necessary	175.65 FS	*175.65 FS
3	1		*RH SILL TRIM PRIMED	Repair	425.55 FS	*- FS
4	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
5	2		*CLIP	Necessary	6.90 FS	*6.90 FS
6	1		*REDO DOOR PANEL (OWNER PAID)	Necessary	250.00 FS	*250.00 FS
					<b>Total Parts (\$\$)</b>	<b>2,820.00</b>
						<b>2,394.45</b>

F=Franchise part. S=SpcNett.

LKK Auto Consultants Pte Ltd/SJZ1186K/21/06/2021 16:50. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT RIGHT DOOR,AND RIGHT SIDE SILL TRIM	New	2,125.00	1,275.00
2	TO SPRAY PAINT FRONT RIGHT DOOR AND RIGHT SIDE SILL TRIM	New	1,711.00	1,539.00
3	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECK ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,544.00</b>	<b>3,415.00</b>

LKK Auto Consultants Pte Ltd/SJZ1186K/21/06/2021 16:50. Not valid without Reference section.

< END OF ESTIMATES >