

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21003419/R1RA3Q2
Date: 16/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070069061
Claimant Vehicle No :	SMF2651Y	Insured Vehicle No :	SLC1009L
Date of Loss:	15/03/2021	Nature of Claim:	TP
		Claim No:	7168531373SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF2651Y		
Make & Model:	VOLKSWAGEN SHARAN, 2.0 TSI 7N24MY (A)	Engine No:	DED032182
Reg. Date:	31/10/2018 (Man. Year: 2018)	Chassis No:	WWZZZ7NZKV000358
Colour:	White	Odometer:	38154 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,338.04	1,950.78	1,387.26	41.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	4,040.00	3,280.00	44.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,658.04	5,990.78	4,667.26	43.79
+ GST 7.00/7.00% (S\$)	746.06	419.35	326.71	43.79

Nett Amount (S\$)	11,404.10	6,410.13	4,993.97	43.79
+ Car Rental (7.0 x S\$120.00/day + 7.00% GST) (S\$)		898.80		
Nett Liability (S\$)		7,308.93		

INSPECTION

Date of Assignment: 19/03/2021

Date Inspected: 19/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

VOLKSWAGEN GROUP SINGAPORE PTE LTD
247 Alexandra Road
Singapore 159934

Adjuster: MOHD RASUL**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED REAR BUMPER	Deformed	1,378.97 FS	*1,378.97 FS
2	1		*BUMPER BRACKET REINFORCEMENT	Serviceable	755.04 FS	*- FS
3	1		*FOAM INSERT	Serviceable	134.37 FS	*- FS
4	1		*ATTACHMENT STRIP RR CTR BRACKET	Serviceable	189.14 FS	*- FS
5	1		*SPOILER SATIN BLACK	Cut	286.09 FS	*286.09 FS
6	1		*CAP PRIMED TOWING COVER	Scratched	72.32 FS	*72.32 FS
7	1		*GUIDE PIECE LHR SIDE BRACKET	Serviceable	81.62 FS	*- FS
8	1		*GUIDE PIECE RHR SIDE BRACKET	Serviceable	81.62 FS	*- FS
9	1		*REFLECTOR RHR	Serviceable	67.42 FS	*- FS
10	1		*VW SIGN BLACK HIGH GLOSS /	Necessary	126.61 FS	*126.61 FS
11	1		*INSCRIPTION CHROME SHARAN	Necessary	86.79 FS	*86.79 FS
12	1		*INSCRIPTION BRIGHT CHROME 380 TSI	Not Necessary	78.05 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)**3,338.04****1,950.78**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
3	LABOUR	New	3,360.00	1,680.00
4	SPRAY PAINTING	New	3,200.00	1,600.00
Gross Labour Cost (S\$)			7,320.00	4,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >