

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III21003423/GQCQ2

**Date:** 06/04/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

**Claimant**  
**Vehicle No :** FBB937M

**Insured Vehicle No :** SHC8141M

Date of Loss: 05/07/2020

Nature of Claim: TP

Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBB937M**

Make & Model: YAMAHA X-1R, 135cc (M)

Engine No: 4S3303000

Reg. Date: 15/05/2009 (Man. Year: 2009)

Chassis No: 4S3303000

Colour: Grey

Odometer: 89072 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 70/90-17

Rear Tyre Size:

80/90-17

Front Left Side: Pirelli 4 mm

Rear Left Side:

Pirelli 4 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 15/03/2021

Date Inspected: 16/03/2021 Inspected At:

Project 8 Motorworks (HQ)  
61 Woodlands Industrial Park E9,,  
#01-03 E9 Premium  
Singapore 757047

Estimated Period of Repair: 0.0 days

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 06 Apr 2021)

**Parts:** N/A YAMAHA X-1R 135cc (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for FBB937M)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**