

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21003426/AGQF3E2

Date: 23/07/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29146646AT2		
Claimant Vehicle No :	SLU8296H	Insured Vehicle No :	SGX2558K		
Date of Loss:	15/03/2021	Nature of Claim:	TP	Claim No:	634528

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU8296H	Engine No:	FB20YB67567
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Chassis No:	JF1SJ5KC5JG101390
Reg. Date:	15/12/2017 (Man. Year: 2017)	Odometer:	100702 km
Colour:	White		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,442.48	5,642.16	6,800.32	54.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,870.00	2,030.00	52.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,342.48	7,512.16	8,830.32	54.03
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	16,342.48	6,000.00	10,342.48	63.29

INSPECTION

Date of Assignment:	16/03/2021	Hua Meng Spray Painting Workshop (HQ)
Date Inspected:	16/03/2021 Inspected At:	No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit
Estimated Period of Repair:	7.0 days	Singapore 417883

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jul 2021)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLU8296H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	660.00 FL	*660.00 FL
2	1		*FRONT BUMPER SIDE HOLDER	O/S Damaged	52.80 FL	*26.40 FL
3	1		*FRONT BUMPER TOP RH SIDE GARNISH	Not Necessary	26.40 FL	*- FL
4	1		*FRONT BUMPER RH LOWER GARNISH	Not Necessary	26.40 FL	*- FL
5	1		*FRONT BUMPER RH FOG LAMP RIM	Cracked	47.50 FL	*47.50 FL
6	1		*FRONT BUMPER RH FOG LAMP	Cracked	467.50 FL	*270.00 FL
7	1		*FRONT BUMPER LOWER LIP	Deformed	880.00 FS	*600.00 FS
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	316.80 FL	*- FL
9	1		*FRONT RH FENDER	Buckled	297.60 FL	*297.60 FL
10	1		*FRONT RH FENDER INNER SHIELD	Deformed	118.80 FL	*118.80 FL
11	1		*FRONT RH HEADLAMP	Cut	2,617.60 FL	*2,400.00 FL
12	1		*FRONT RH HEADLAMP LOWER BRACKET	Cracked	39.60 FL	*39.60 FL
13	1		*FRONT GRILLE	Not Necessary	380.20 FL	*- FL
14	1		*FRONT SUPPORT PANEL	Repair	480.70 FL	*- FL
15	1		*FRONT RH LOWER ARM	Bent	602.80 FL	*558.00 FL
16	1		*FRONT RH SHOCK ABSORBER	Bent	400.00 FL	*400.00 FL
17	1		*FRONT RH DRIVE SHAFT	Not Necessary	864.50 FL	*- FL
18	1		*FRONT RH KNUCKLE ARM	Damaged	377.30 FL	*377.30 FL
19	1		*FRONT RH KNUCKLE ARM BEARING	Damaged	297.00 FL	*297.00 FL
20	1		*FRONT RH LINKAGE BRACKET	Bent	110.50 FL	*110.50 FL
21	1		*FRONT RH SUPPORT ARM	Not Necessary	591.80 FL	*- FL
22	1		*FRONT ENGINE LOWER COVER	Not Necessary	190.10 FL	*- FL
23	1		*STEERING RACK ASSY	Repair	2,799.70 FL	*- FL
24	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
25	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS
26	1		*FRONT RH SPORT RIM	Cut	1,650.00 FS	*500.00 FS
27	1		*FRONT RH TYRE	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,795.60	6,762.70
- List Item Discount on L Items 20.00/20.00% (\$)	2,353.12	1,120.54
Total Parts (\$)	12,442.48	5,642.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	150.00	120.00
2	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
3	REMOVE & REINSTALL AIRCON FILL IN GAS	New	150.00	0.00
4	REMOVE & REINSTALL FRONT SUSPENSION	New	600.00	370.00
5	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,500.00	650.00
6	RESPRAY PAINTING	New	1,300.00	600.00
7	TUFF KOTE	New	100.00	50.00
Gross Labour Cost (\$\$)			3,900.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >