Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Date: 22 Jun 2021 Koh Ming Shao

Preliminary Advice

Insured Vehicle No : SGX2558K

TP Vehicle No : SLU8296H : 15/03/2021 Accident Date Make : SUBARU FORESTER Assignment Date : 16/03/2021

Date of Inspection : 16/03/2021 Est. Duration of Repair : 7

Inspection At : HUA MENG SPRAY PAINTING WORKSHOP (HQ)

NO 1 KAKI BUKIT AVENUE 6, #01-61 AUTOBAY@KAKI BUKIT

SINGAPORE 417883

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,342.48	
Revised Amount	:S\$	9,428.16	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	9,428.16	
Lump Sum Repair	:S\$	7.500.00	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is economical for repair
()	The vehicle is not economical for repair
()	Part-by-Part repair
()	Lump Sum repair
()	The above survey was conducted on a 'without prejudice' basis.