

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21003427/ATF3N2**Date:** 07/09/2021**REFERENCE**

Insured/Claimant:	ANG POH LI	Policy No:	1800112182	
Date of Loss:	12/03/2021	Nature of Claim:	OD	Claim No: 9168842517SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME2864E		
Make & Model:	AUDI A3, 1.4 TFSI (A)	Engine No:	CZE697609
Reg. Date:	25/09/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8VXJA129745
Colour:	White	Odometer:	29805 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,956.00	11,453.04	9,502.96	45.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,402.00	6,402.00	5,000.00	43.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,358.00	17,855.04	14,502.96	44.82
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	32,058.00	17,555.04	14,502.96	45.24
+ GST 7.00/7.00% (S\$)	2,244.06	1,228.85	1,015.21	45.24
Nett Amount (S\$)	34,302.06	18,783.89	15,518.17	45.24

INSPECTION

Date of Assignment:	16/03/2021		
Date Inspected:	16/03/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	9.0 days		

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	2,016.00 FS	*1,612.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	39.00 FS	*- FS
4	1		*FRONT BUMPER LOWER GRILLE-CENTER	Cracked	160.00 FS	*128.00 FS
5	1		*FRONT BUMPER LOWER COVER-RH/CTR	Not Necessary	594.00 FS	*- FS
6	1		*FRONT RADIATOR OUTER GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
7	1		*FRONT RADIATOR END PLATE	Cracked	191.00 FS	*152.40 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Deformed	188.00 FS	*150.00 FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	189.00 FS	*151.20 FS
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	795.00 FS	*- FS
11	1		*FRONT BUMPER COVER	Cracked	122.00 FS	*97.20 FS
12	1		*LOW TONE HORN-RH	Not Necessary	200.00 FS	*- FS
13	1		*FRONT FENDER-RH	Buckled	851.00 FS	*680.40 FS
14	1		*FRONT FENDER POP RIVET	Not Necessary	27.00 FS	*- FS
		8 Pcs				
15	1		*ATTACHMENT PARTS FOR FRONT FENDER-RH	Not Necessary	72.00 FS	*- FS
16	1		*FRONT FENDER CENTER BRACKET-RH	Not Necessary	48.00 FS	*- FS
17	1		*FRONT FENDER REAR BRACKET-RH	Not Necessary	28.00 FS	*- FS
18	1		*FRONT FENDER BRACE	Not Necessary	96.00 FS	*- FS
19	1		*FRONT FENDER CLOSING ELEMENT	Not Necessary	62.00 FS	*- FS
20	1		*FRONT WHEEL HOUSING LINER	Not Necessary	169.00 FS	*- FS
21	1		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	57.00 FS	*- FS
22	1		*FRONT BONNET	Dented	2,745.00 FS	*2,196.00 FS
23	1		*ATTACHMENT PARTS FOR BONNET	Not Necessary	165.00 FS	*- FS
24	2		*FRONT BONNET LID HINGE-LH/RH	Not Necessary	124.00 FS	*- FS
25	1		*FRONT BONNET EDGE PROTECTION	Necessary	28.00 FS	*22.00 FS
26	1		*FRONT BONNET CATCH HOOK	Not Necessary	90.00 FS	*- FS
27	2		*FRONT BONNET STRIKER-LH/RH	Not Necessary	220.00 FS	*- FS
28	1		*FRONT BONNET CATCH HOOK	Not Necessary	63.00 FS	*- FS
29	2		*FRONT BONNET LOCK W/MICRO SWITCH	Not Necessary	427.00 FS	*- FS
30	1		*FRONT BONNET BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
31	1		*FRONT BONNET RELEASE CABLE COVER	Not Necessary	10.00 FS	*- FS
32	1		*FRONT BONNET SOUND INSULATOR	Not Necessary	219.00 FS	*- FS
33	1		*LED HEADLIGHT-RH	Cracked	5,455.00 FS	*4,364.00 FS
34	1		*LED HEADLIGHT LIFT CYLINDER-RH	Not Necessary	142.00 FS	*- FS
35	1		*LED HEADLIGHT LIFT CYLINDER-HOSE	Not Necessary	68.00 FS	*- FS
36	1		*FRONT RADIATOR LOCK CARRIER	Cracked	727.00 FS	*581.60 FS
37	1		*A/C CONDENSER W FLUID RESERVOIR	Not Necessary	589.00 FS	*- FS
38	1		*FRONT RADIATOR TEMP SENSOR BRACKET	Not Necessary	19.00 FS	*- FS
39	1		*FRONT RADIATOR-ADDITIONAL	Not Necessary	859.00 FS	*- FS
40	1		*FRONT RADIATOR	Not Necessary	951.00 FS	*- FS
41	1		*COOLANT FOR RADIATOR	Necessary	95.00 FS	*75.52 FS
42	1		*FRONT RADIATOR AIR GUIDE-RH	Cracked	25.00 FS	*19.44 FS
43	1		*FRONT RADIATOR OUTER AIR GUIDE SEAL-RH	Not Necessary	8.00 FS	*- FS
44	1		*FRONT RADIATOR UPPER AIR GUIDE SEAL-CENTER	Not Necessary	12.00 FS	*- FS
45	1		*FRONT NUMBER PLATE	Dented	60.00 FS	*60.00 FS
46	1		*SUNDRIES	Necessary	300.00 FS	*37.68 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **20,956.00** **11,453.04**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCON CONDENSER,ADDITIONAL RADIATOR AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
3	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER,BONNET AND RHS HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,300.00	2,750.00
5	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.BONNET	New	3,000.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			11,402.00	6,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >