

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21003432/ARS3Q2
Date: 16/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100079820
Claimant Vehicle No :	SJN4210S	Insured Vehicle No :	SFB1862R
Date of Loss:	13/03/2021	Nature of Claim:	TP
		Claim No:	6085614133SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN4210S		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	3ZZ4865793
Reg. Date:	16/02/2009 (Man. Year: 2009)	Chassis No:	MR053ZEE106140142
Colour:	Silver	Odometer:	325834 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,608.70	3,332.21	9,276.49	73.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,280.00	1,850.00	59.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,738.70	4,612.21	11,126.49	70.70
Approved Total (Overridden) (S\$)		3,700.00		

Nett Amount (S\$)	15,738.70	3,700.00	12,038.70	76.49
		+ Loss of Use (4.0 x S\$80.00/day) (S\$)	320.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	4,022.00	

INSPECTION

Date of Assignment: 15/03/2021

Date Inspected: 15/03/2021

Estimated Period of Repair: 5.0 days

Inspected At: SM Automotive (HQ)
756 JURONG WEST STREET 74, #12-60
Singapore 640756

Adjuster: Lee Su Li**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	481.85 F	*- FL
2	2		*FRONT BONNET HINGE	Not Necessary	242.70 F	*- FL
3	1		*FRONT BONNET LOCK	Not Necessary	182.10 F	*- FL
4	1		*FRONT BONNET INSULATOR	Not Necessary	374.50 F	*- FL
5	1		*FRONT GRILLE	Not Necessary	381.10 F	*- FL
6	1		*FRONT BUMPER	Deformed	561.85 F	*561.85 FL
7	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
8	1		*FRONT BUMPER EMBLEM LOGO	Necessary	61.75 F	*61.75 FL
9	1		*FRONT BUMPER TOP RUBBER	Not Necessary	191.60 F	*- FL
10	1		*FRONT BUMPER CENTRE LOWER GARNISH	Not Necessary	182.20 F	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	374.40 F	*- FL
12	1		*FRONT L/H BUMPER SIDE RETAINER	Necessary	122.10 F	*34.00 FL
13	1		*FRONT L/H BUMPER FOG LAMP	Cracked	374.10 F	*288.20 FL
14	1		*FRONT L/H BUMPER FOG LAMP COVER	Cracked	174.40 F	*174.40 FL
15	1		*FRONT L/H HEAD LAMP	Cracked	378.85 F	*378.85 FL
16	1		*FRONT L/H FENDER	Buckled	374.10 F	*374.10 FL
17	1		*FRONT L/H FENDER COWLING	Not Necessary	182.10 F	*- FL
18	10		*FRONT L/H FENDER COWLING CLIP	Not Necessary	65.00 F	*- FL
19	1		*FRONT L/H RIM	Cut	680.00 FS	*450.00 FS
20	1		*FRONT L/H TYRE	Not Necessary	350.00 F	*- FL
21	1		*FRONT L/H LOWER ARM	Bent	581.90 F	*375.00 FL
22	1		*FRONT L/H KNUCKLE ARM	Damaged	561.60 F	*561.60 FL
23	1		*FRONT L/H KNUCKLE ARM BEARING	Necessary	191.80 F	*191.80 FL
24	1		*FRONT L/H SHOCK ABSORBER	Bent	381.90 F	*381.90 FL
25	1		*FRONT L/H DRIVE SHAFT	Not Necessary	1,712.40 F	*- FL
26	1		*FRONT STEERING RACK	Not Necessary	1,822.50 F	*- FL
27	1		*FRONT GRILLE ASSY	Not Necessary	559.30 F	*- FL
28	8		*FRONT GRILLE CLIP	Not Necessary	52.00 F	*- FL
29	1		*FRONT GRILLE EMBLEM LOGO	Not Necessary	43.10 F	*- FL
30	1		*FRONT BUMPER LOWER CENTER GARNISH	Cracked	123.50 F	*123.50 FL
31	1		*FRONT AIR COOLER TANK	Cracked	374.50 F	*241.00 FL
32	1		*FRONT AIR COOLER TANK DUCT	Not Necessary	120.00 F	*- FL
33	1		*FRONT AIR COOLER TANK HOSE	Deformed	284.50 F	*65.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)**12,608.70****4,292.95**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 0.00/25.00% (S\$)					0.00	960.74
Total Parts (S\$)					12,608.70	3,332.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT L/H UNDERCARRIAGE & STEERING RACK	New	380.00	220.00
2	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
3	TO CHECK WIRING	New	100.00	30.00
4	TUFF KOTE	New	150.00	50.00
5	TOWING FEE	New	150.00	0.00
6	PANEL BEATING	New	1,000.00	500.00
7	SPRAY PAINTING	New	1,200.00	400.00
Gross Labour Cost (S\$)			3,130.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >