



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0418 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

*Requ
paper survey*

Vehicle Inspection Report

To: Lim Siew Kiat
C/o: 160 Sin Ming Drive #05-20
Sin Ming AutoCity (S) 575722

Date of report: 30.12.2019
Date of request: 27.11.2019
Date of inspection: 27.11.2019
Date of accident: 20.10.2019
Claim type: Third Party Claim

Report No: AAS/2019/582

Particulars of affected vehicle:

Registration no: FQ4656X
Make/Model: Honda Steed VLS (Motorcycle)
Year of registration: 1998
Colour: Black

Odometer: 75100 km
Engine Capacity: 398 cc
Engine no: NC25E3001838
Chassis no: NC371001827

Condition of tires:

Front: 5mm
Make: Metzeler
Rear: 5mm
Make: Metzeler

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : In order
Footbrake : In order
Steering : In order
Apparent engine modification : Nil

The Assignment

The inspection was conduct at M/s. Lim Motor Pte Ltd
160 Sin Ming Drive #05-20
Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

Assessment

Repairer's estimate: \$ 6,050.40
Revised estimate: \$ 5,634.40
Recommended reserve: \$ 4,500.00 (Lump sum)

Estimated normal duration of repairs : 4 Working days



**ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS**

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7896

Email: absolute.app.svcs@gmail.com

Vehicle No: FQ4656X

Report No: AAS/2019/582

W/O PREJUDICE

Point of impact

At the rear portion.

General description of damages

The rear rim, rear fender, tail light, rear license plate base, subframe, swing arm, bodyframe, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Lim Motor Pte Ltd as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$5,634.40

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$4,500.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 4 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 107 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
 160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
 Mobile: 9688-0413 Fax: 6266-7396
 Email: absolute.app.svcs@gmail.com

Vehicle No: FQ4656X

Report No: AAS/2019/582

Appraisement Schedule

S/N	Parts Description	Qty	Condition	Repairer's Est	Revised Est
1	Rear spoke rim	1	Dented	\$ 692.00	\$ 692.00
2	Swing arm	1	Distorted	\$ 970.00	\$ 970.00
3	Swing arm axle	1	Bent	\$ 75.00	\$ 75.00
4	Drive chain <i>X SVC</i>	1	Necessary	\$ 123.00	\$ 123.00 X
5	Tail light	1	Broken	\$ 160.00	\$ 160.00
6	Rear license plate light	1	Broken/Missing	\$ 60.00	\$ 60.00
7	Rear license plate base	1	Dented	\$ 291.00	\$ 291.00
8	Rear reflector	1	Broken	\$ 16.00	\$ 16.00
9	Rear fender	1	Dented/Distorted	\$ 277.00	\$ 277.00
10	Subframe <i>repair</i>	1	Dented/Distorted	\$ 850.00	\$ 850.00 X
11	Front footrest RH	1	Grazed	\$ 72.00	\$ 72.00
12	Exhaust muffler	2	Grazed	\$ 745.00	\$ 1,490.00
13	Front brake lever	1	Dented/Grazed	\$ 60.00	\$ 60.00
14	Handlebar	1	Bent/Repair	\$ 220.00	-
				Total:	\$ 5,356.00
				-10%	\$ 535.60
				List total:	\$ 4,820.40
				<i>4163</i>	
				<i>10%</i>	
				<i>3746.70</i>	
1	Rear foot plate	1set	RH Dented	\$ 70.00	\$ 70.00
2	Rear tyre <i>X SVC</i>	1	Affected	90% \$ 180.00	\$ 162.00 X
3	Bulb	2	Broken	\$ 5.00 \$ 10.00	\$ 10.00
4	Rear number plate	1	Dented/Missing	\$ 20.00	\$ 20.00
				Special nett total:	\$ 280.00
				<i>100</i>	
				Parts Total:	\$ 5,100.40

S/N	Labour Description	Repairer's Est	Revised Est
1	Renew rear rim & tyre.	\$ 50.00	\$ 20.00
2	Repair, straighten & refurbish body frame.	\$ 300.00 <i>150</i>	\$ 250.00
3	Labour to renew damaged parts.	\$ 500.00 <i>250</i>	\$ 400.00
4	Towing charges. 2x	\$ 100.00 <i>40</i>	\$ 80.00
		Labour Total:	\$ 750.00
		<i>4306.70</i>	
		<i>20%</i>	
		Grand Total:	\$ 6,050.40

The final adjusted lump sum amount is \$4,500.00 *3745.36*

Under normal circumstances, the repair should be completed within a reasonable period of 4 working days.

107 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.

** Repair limit 1.8k*

4 days