

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE I	F	Ref:	CS3/ASM21003443/Gvf3e2	
	8 SHENTON WAY TOWERSINGAPOR	[Date:	22/03/2021	
	ATTN : TAN JUN H	ONG	(Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 3540C	Veh. Inspected		JPV 4670
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S1M035ED	Excess (\$)		0.00
	Assign From	TAN JUN HONG	Assign Date		16/03/2021
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA 135LC	c.c		134
	Engine No.	HIDDEN	Year of Reg.		2013
	Chassis No.	PMYKG0250D0029909	Colour		BLACK
	Odometer	1430 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	70/90-17	MAXXIS		5 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	80/90-17	MAXXIS		5 mm
	L/H Rear Tyre				mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION,N/S AND O/S BODY.				
5. General Information					
	Accident Date	12/03/2021	Inspect Date / Ti	ime	17/03/2021 (05:00 PM)
	Survey held at	ONG MOTOR TRADING			
		NO. 464 MACPHERSON ROAD SINGAPORE 368182			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM21003443/Gvf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.