

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003447/KPA3Q2
Date: 18/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993762
Claimant Vehicle No :	SKE1155Z	Insured Vehicle No :	SJJ21T
Date of Loss:	12/03/2021	Nature of Claim:	TP
		Claim No:	3550904087SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE1155Z	Engine No:	G4FGCU467008
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHDH41CMCU423160
Reg. Date:	09/02/2012 (Man. Year: 2012)	Odometer:	220025 km
Colour:	Metallic Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	West Lake 8 mm	Rear Left Side:	West Lake 8 mm
Front Right Side:	West Lake 8 mm	Rear Right Side:	West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,980.80	7,935.48	2,045.32	20.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	3,130.00	660.00	17.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,770.80	11,065.48	2,705.32	19.65
Approved Total (Overridden) (S\$)		5,800.00		

Nett Amount (S\$)	13,770.80	5,800.00	7,970.80	57.88
+ Car Rental (12.0 x S\$100.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,007.45		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment: 16/03/2021

Date Inspected: 17/03/2021

Estimated Period of Repair: 12.0 days

Inspected At:

Guan Motor Works (HQ)
 176 Sin Ming Drive #02-03 Sin Ming Autocare
 Singapore 575721

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	474.60 FL	*474.60 FL
2	1		*FRONT BUMPER TOW COVER	Dented	26.00 FL	*26.00 FL
3	1		*FRONT BUMPER RH FOG LAMP	Serviceable	115.40 FL	*- FL
4	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	32.00 FL	*32.00 FL
5	1		*FRONT BUMPER INNER FOAM	Cracked	110.70 FL	*110.70 FL
6	1		*FRONT BUMPER INNER REINFORCEMENT	Bent	695.80 FL	*695.80 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
8	1		*RH HEADLAMP	Mtg Cracked	1,198.80 FL	*1,198.80 FL
9	1		*FRONT RH FENDER	Repair	966.80 FL	*- FL
10	1		*REAR BUMPER	Bent	459.40 FL	*459.40 FL
11	1		*REAR BUMPER LH REFLECTOR	Cracked	32.00 FL	*32.00 FL
12	1		*REAR BUMPER SIDE RETAINER	N/S Cracked	88.60 FL	*44.30 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
14	5		*REAR BUMPER INNER BRACKET (TOP & BOTTOM)	Cracked (2 PCS ONLY)	180.00 FL	*72.00 FL
15	1		*REAR BUMPER INNER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
16	1		*REAR BUMPER INNER REINFORCEMENT LH BRACKET	Bent	75.30 FL	*75.30 FL
17	1		*LH TAILLAMP	Broken	876.80 FL	*876.80 FL
18	1		*LH TAILLAMP PANEL	Bent	162.00 FL	*162.00 FL
19	1		*REAR BOOT LID	Bent	1,528.10 FL	*1,528.10 FL
20	1		*REAR BOOT LH SIDE REFLECTOR /LAMP	Cracked	664.20 FL	*664.20 FL
21	1		*REAR BOOT CENTRE H LOGO	Necessary	34.00 FL	*34.00 FL
22	1		*REAR BOOT LH HYUNDAI EMBLEM	Necessary	56.00 FL	*56.00 FL
23	1		*REAR BOOT RH ELANTRA EMBLEM	Necessary	48.80 FL	*48.80 FL
24	1		*REAR BOOT HINGES	N/S Bent	178.00 FL	*89.00 FL
25	1		*REAR BOOT INNER TRIM	Deformed	306.00 FL	*306.00 FL
26	1		*SET REAR BOOT INNER TRIM CLIPS	Necessary	60.00 FL	*60.00 FL
27	1		*REAR BOOT TOP LOCK	Dented	116.20 FL	*116.20 FL
28	1		*REAR BOOT LOWER LOCK CATCH	Repair	24.10 FL	*- FL
29	1		*REAR BOOT WEATHERSTRIP (50%)	Distorted / Dented	77.12 FS	*48.20 FS
30	1		*REAR END PANEL	Bent	382.40 FL	*382.40 FL
31	1		*REAR END PANEL TOP GARNISH	Distorted	65.40 FL	*65.40 FL
32	1		*REAR SPARE TYRE PANEL	Repair	647.00 FL	*- FL
33	1		*REAR SPARE TYRE TOP BOARD	Serviceable	219.40 FL	*- FL
34	1		*REAR LH FENDER	Buckled	1,096.00 FL	*1,096.00 FL
35	1		*REAR LH FENDER UNDER SPLASH SHIELD	Serviceable	64.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET REAR FENDER UNDER SPLASH SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
37	1		*REAR LH FENDER 1/4 GLASS MOULDING	Necessary	53.00 FL	*53.00 FL
38	1		*REAR LH FENDER INNER SIDE TRIM	Deformed	348.00 FL	*348.00 FL
39	1		*SET REAR FENDER INNER SIDE TRIM CLIPS	Necessary	60.00 FL	*60.00 FL
40	1		*FRONT NUMBER PLATE	Serviceable	45.00 FS	*- FS
41	1		*SET REVERSE SENSORS	Shorted	250.00 FS	*200.00 FS
42	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
43	1		*SET REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
44	1		*SET REAR END PANEL SEALANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,346.72	9,839.80
- List Item Discount on L Items 20.00/20.00% (\$)	2,365.92	1,904.32
Total Parts (\$)	9,980.80	7,935.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR REMOVE /REFIT ,PANEL BEAT AND REPLACEMENT OF DAMAGES	New	1,600.00	1,400.00
2	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES	New	1,400.00	1,200.00
3	TO CHECK WIRINGS AND LIGHTINGS FOR FRONT & REAR PORTION	New	80.00	40.00
4	TO REMOVE ,REFIT REAR WINDSCREEN GLASS	New	140.00	120.00
5	TO REMOVE,REFIT REAR LH FENDER 1/4 GLASS	New	100.00	50.00
6	TO TRANSFER REAR BOOT LID FITTINGS	New	80.00	60.00
7	TO REMOVE ,REFIT REVERSE SENSORS	New	70.00	50.00
8	TO REMOVE ,REFIT ROOF LINING ,REAR CUSHION AND ATTACHMENTS	New	200.00	120.00
9	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	120.00	90.00
Gross Labour Cost (\$\$)			3,790.00	3,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >