



明輝汽車服務私人有限公司
BH AUTO SERVICES PTE LTD

Repairer Estimates

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC20P00215300	Date of Loss:	10/03/2021
Vehicle Reg. No.:	SLV4491G	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHITRA DEVI D/O KASIVISWANATHAN		

Make/Model:	SUBARU FORESTER, 2.0 I (A)	Vehicle Reg. Date:	29/12/2017
Vehicle Colour:	BROWN		
Engine No:	FB20YB72715	Chassis No:	JF1SJ5KC5JG101685
Odometer:	89442 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	4 ✓

Not Notified
Running B4 pay
\$4517.60

Present Location: BH AUTO SERVICES PTE LTD (SIN MING)

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	3,405.60
Labour	0.00
Paintwork Labour	1,200.00
Towing	1,730.00
	0.00
Gross Total (S\$)	6,335.60
+ GST 7.00% (S\$)	443.49
Nett Amount (S\$)	6,779.09

This claim is handled by: MOO WEN ZHENG

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 16 Mar 2021)

Part Source: MRM-SG

SUBARU FORESTER 2.0 i (A) (Catalogue: Merimen Singapore 1.0)

Parts: M1-SUV

(Price-denominated Standard List)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: BH Auto Services Pte Ltd/SLV4491G/16/03/2021 12:05

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers, and the END OF ESTIMATES marker on the last estimate page.

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		Bonnet			BH *600.00 F ✓
2	10		Bumper clip, front	0.00	0.00	M *20.00 F ✓
3	1		Bumper reinforcement, front	0.00	0.00	R *200.00 F ✓
4	1		Headlamp LH	0.00	0.00	BH *1,700.00 F ✓
5	1		Headlamp panel LH	0.00	0.00	R *38.00 F ✓
6	1		*Front bumper side retainer LH	0.00	0.00	SM *15.00 F ✓
7	1		*Front bumper sponge	0.00	0.00	SM *125.00 F ✓
8	1		*Head lamp washer cover LH	0.00	0.00	Mi *58.00 F ✓
9	1		*Head lamp washer motor LH	0.00	0.00	SM *150.00 F ✓
10	1		*Head lamp washer nozzle LH	0.00	0.00	SM *85.00 F ✓
11	1		*Front fender shield LH	0.00	0.00	SM *85.00 F ✓
12	10		*Front fender shield clips	0.00	0.00	NN *20.00 F ✓
Sub Total (S\$)						400.00
+ Margin on L,N Items 10.00% (S\$)						3,096.00
Total Parts (S\$)						3,405.60

BH Auto Services Pte Ltd/SLV4491G/16/03/2021 12:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Items on Miscellaneous Items

Repairer Estimates

Estimates on Labour

No Particulars

Paintwork Labour	Lab.Type	Amount
1 Provide skill and labour to remove all damaged parts, panel beat, cut and well if necessary and align all panel and reinstall all damaged parts	New	600 1,200.00
2 Provide skill and labour to disconnect and check electrical wiring	New	20 80.00
3 Provide skill and labour to check and readjust wheel alignment	New	150.00 X
4 Provide skill and labour to uninstall and replace new bonnet	New	300.00 X
Labour Items		
5 Provide skill and labour to putty all damaged parts & panel to respray with 2k paint with oven spray booth facilities (Type comment here)	New	800 1,200.00

Gross Labour Cost (S\$) 2,930.00

BH Auto Services Pte Ltd/SLV4491G/16/03/2021 12:05. Not valid without Reference section.
Generated using Meritmen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: