7/6/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG21003455/T1PA3Q2

Date:

06/07/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

2100476033

Claimant Vehicle No:

SH8229M 16/03/2021 Insured Vehicle No:

Nature of Claim:

GBF1710Y TP

Claim No:

9598077105SG

KMHLB41UMGU091903

595218 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH8229M

Make & Model: HYUNDAI 140, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDGU669711

Reg. Date: 21/07/2016 (Man. Year: 2016)

Odometer:

Colour: Blue

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Footbrake (Serviceable):

Chassis No:

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: No

Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Front Right Side: West Lake 6 mm West Lake 6 mm

Rear Right Side:

Rear Left Side:

West Lake 6 mm

West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,948.00	2,948.00	0.00	0.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,300.00	980.00	320.00	24.62
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,248.00	3,928.00	320.00	7.53
	Approved Total (Overridden) (S\$)		3,150.00		

(S\$)	4,248.00	3,150.00	1,098.00	25.85
+ GST 7.00/7.00% (S\$)	297.36	220.50	76.86	25.85
Nett Amount (S\$)	4,545.36	3,370.50	1,174.86	25.85
+ Loss of Use (2.0 x S\$50.00/day) (S\$) + Car Rental (2.0 x S\$110.67/day) (S\$) + Doc/Search Fee (S\$) Nett Liability (S\$)		100.00		
		221.34		
		2.00		
		3,693.84		
Global Su	ım Settlement (S\$)	3,690.00		

INSPECTION

Date of Assignment: 16/03/2021

ComfortDelGro Engineering Pte Ltd (Loyang)

Inspected At: 59 Loyang Drive Date Inspected: 16/03/2021 Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID CHEW HSIAO TONG Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER W LIP & FOG LAMP	Deformed	1,052.20 FL	*1,052.20 FL
2	1		*LAMP ASSY -HEAD RH	Cut	1,800.00 FL	*1,800.00 FL
3	1		*PANEL -FENDER RH	Bent	663.00 FL	*663.00 FL
4	1		*BRACKET -FR BUMPER SIDE RH	Necessary	44.80 FL	*44.80 FL
5	1		*ADVERTISEMENT STICKER -FENDER	Cut	100.00 FS	*100.00 FS
F=Fra	nchise	part. S=SpcNett. L	_=ListItemDisc.			
				Sub Total (S\$)	3,660.00	3,660.00
				- List Item Discount on L Items 20.00/20.00% (S\$)	712.00	712.00
				Total Parts (S\$)	2,948.00	2,948.00
	Report was unsubmitted during this print-out.					

7/6/2021 Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab				
1	PANEL BEATING	New	600.00	420.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	30.00
		Gross Labour Cost (S\$)	1,300.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >