

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21003456/T1TD3E2

Date: 04/05/2021

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR003604		
Claimant Vehicle No :	SHA5383L	Insured Vehicle No :	SGR933E		
Date of Loss:	15/03/2021	Nature of Claim:	TP	Claim No:	M2101259

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA5383L	Engine No:	G4LEKU407489
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU189571
Reg. Date:	11/03/2020 (Man. Year: 2019)	Odometer:	145440 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,165.32	1,051.12	1,114.20	51.46
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	820.00	630.00	190.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,996.32	1,692.12	1,304.20	43.53
+ GST 7.00/7.00% (S\$)	209.74	118.45	91.29	43.53
Nett Amount (S\$)	3,206.06	1,810.57	1,395.49	43.53

INSPECTION

Date of Assignment:	16/03/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	16/03/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2021)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA5383L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	-	*459.40 FL
2	1		*REAR BUMPER CTR MOULDING	Deformed	451.25 FL	-	*451.25 FL
3	1		*REAR BUMPER LWR MOULDING	Repair	155.00 FL	-	*- FL
4	1		*REAR BUMPER BEAM	Not Necessary	394.80 FL	-	*- FL
5	2		*REAR BUMPER STAY RH/LH	Not Necessary	276.20 FL	-	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
7	1		*REAR BUMPER REFLECTOR LH	Not Necessary	41.45 FL	-	*- FL
8	1		*REAR BUMPER FOGLAMP	Not Necessary	201.50 FL	-	*- FL
9	1		*REAR BUMPER TOW COVER	Not Necessary	98.80 FL	-	*- FL
10	1		*REAR BUMPER MAT	Necessary	50.00 F	-	*50.00 F
11	1		*REVERSE SENSOR	Not Necessary	180.00 F	-	*- F
12	2		*REAR FENDER ADVERTISEMENT STICKER RH/LH	Necessary	200.00 F	-	*200.00 F
13	1		*REAR NO.PLATE W/TRIM COVER	Cracked	55.00 F	-	*55.00 F
					Sub Total (\$)	2,585.40	1,237.65
					- List Item Discount on L Items 20.00/20.00% (\$)	420.08	186.53
					Total Parts (\$)	2,165.32	1,051.12

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			820.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >