

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 3018L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DENTED / WARPED	955.80	616.00
1	SET FRONT BUMPER CLIPS	NECESSARY	40.00	40.00
1	FRONT BUMPER FOG LAMP-LH	SERVICEABLE	328.10	-
1	FRONT BUMPER FOG LAMP COVER-LH	MTG DISTORTED	55.10	55.10
1	FRONT BUMPER FOG LAMP COVER CHROME MOULDING-LH	DENTED	85.90	85.90
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	365.50	-
1	FRONT BUMPER SIDE RETAINER-LH	CRACKED	36.30	36.30
1	FRONT BUMPER SIDE RETAINER-RH	SERVICEABLE	36.30	-
1	FRONT FENDER-LH	TO REPAIR SEE LABOUR	544.00	-
1	FRONT FENDER LAMP-LH	MTG CRACKED	75.50	75.50
1	FRONT FENDER SPLASH SHIELD-LH	SERVICEABLE	245.30	-
1	SET FRONT FENDER SPLASH SHIELD CLIP	NOT NECESSARY	40.00	-
1	FRONT GRILLE	SERVICEABLE	285.50	-
1	FRONT HEADLAMP-LH	SERVICEABLE	825.10	-
1	FRONT HEADLAMP LOWER BRACKET-LH	SERVICEABLE	65.90	-
	LESS 20% DISCOUNT		-	-181.76
			3,984.30	727.04
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT FENDER-LH.		800.00	200.00
	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		800.00	200.00
	TO CHECK WIRING FUNCTIONS.		60.00	15.00
			1,660.00	415.00
	GRAND TOTAL		5,644.30	1,142.04



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			1,142.04	
-----------------------------	--	--	----------	--

Report Ref No. CS/LPC21003461/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser