

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21003469/GVD3E2**Date:** 24/05/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900019657
Claimant Vehicle No :	FBG4399M	Insured Vehicle No :	SJY7900G
Date of Loss:	08/03/2021	Nature of Claim:	TP
		Claim No:	3256832814SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBG4399M	Engine No:	50C360506
Make & Model:	YAMAHA JUPITER LC135, 135cc	Chassis No:	MH350C002CK360806
Reg. Date:	17/07/2012 (Man. Year: 2012)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	134 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90-17	Rear Tyre Size:	90/80-17
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	17/03/2021	Inspected At:	Mcs Auto (HQ) 1100 Serangoon Rd Singapore 328195
Date Inspected:	17/03/2021		
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$1,500.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIM	Cut	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Broken	0.00 F	*- F
3	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
4	1		*FRONT FORK BRACKET	Distorted	0.00 F	*- F
5	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
6	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
7	1		*FRONT WING MIRROR LH	Missing	0.00 F	*- F
8	1		*ERP BRACKET	Bent	0.00 F	*- F
9	1		*ERP UNIT	Cut	0.00 F	*- F
10	1		*HANDLE BAR	Bent	0.00 F	*- F
11	1		*HANDLE BAR GRIP	Necessary	0.00 F	*- F
12	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
13	1		*CLUTCH LEVER	Bent	0.00 F	*- F
14	1		*HAND BRAKE LEVER	Cut	-	*- F
15	1		*SIDE FAIRING LH	Cut	0.00 F	*- F
16	1		*SIDE FAIRING TOP GARNISH	Cut	0.00 F	*- F
17	1		*FAIRING TOP GARNISH	Cracked	0.00 F	*- F
18	1		*FRONT TRAY	Cut	0.00 F	*- F
19	1		*IU POUCH	Torn	0.00 F	*- F
20	1		*FRONT FOOT REST LH	Bent	0.00 F	*- F
21	1		*FOOT GEAR SHIFTER	Distorted	0.00 F	*- F
22	1		*REAR FENDER WHEEL GUARD	Cracked	0.00 F	*- F
23	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
24	1		*REAR BOX BRACKET	Distorted	0.00 F	*- F
25	1		*STICKER	Necessary	0.00 F	*- F
26	1		*TAILBOARD	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >