

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO21003474/KQvf3e2
	50 RAFFLES PLAC TOWER SINGAPO	CE #03-03 SINGAPORE LAND RE 048623		Date:	01/04/2021
				Code:	SMO
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLN 961K	Veh. Inspected	d	SLG 9738S
	Policy No.	D20MTPV01004420	Coverage (\$)		0.00
	Claim No.	CMTD2100828/SYH	Excess (\$)		0.00
	Assign From	GRACE TEO	Assign Date		17/03/2021
2.	Vehicle Particulars & Condition				
	Make & Model	HONDA JAZZ 1.4M	c.c		1339
	Engine No.	HIDDEN	Year of Reg.		2007
	Chassis No.	JHMGD17507S221748	Colour		YELLOW
	Odometer	195930 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	185/55 R15	BRIDGESTONE		6 mm
	L/H Front Tyre	185/55 R15	BRIDGESTONE		6 mm
	R/H Rear Tyre	185/55 R15	BRIDGESTONE		6 mm
	L/H Rear Tyre	185/55 R15	BRIDGESTONE		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
5.	General Information				
	Accident Date	15/03/2021	Inspect Date /	Time	17/03/2021 (02:15 PM)
	Survey held at	MJE MOTOR	•		
	BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				

Report Ref No. CS3/SMO21003474/KQvf3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser