

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III21003476/APS3Q2
Date: 08/07/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005568_01
Claimant Vehicle No :	SFS1866R	Insured Vehicle No :	YN165M
Date of Loss:	15/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001156

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFS1866R		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Engine No:	L15B6021040
Reg. Date:	05/10/2020 (Man. Year: 2019)	Chassis No:	GK82100868
Colour:	White	Odometer:	4696 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,160.00	1,968.64	1,191.36	37.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,520.00	550.00	26.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,230.00	3,488.64	1,741.36	33.30
+ GST 7.00/7.00% (S\$)	366.10	244.20	121.90	33.30

Nett Amount (S\$)	5,596.10	3,732.84	1,863.26	33.30
		+ Loss of Use (6.0 x S\$60.00/day) (S\$)	360.00	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	4,100.29	
		Global Sum Settlement (S\$)	4,100.00	

INSPECTION

Date of Assignment: 17/03/2021

Date Inspected: 23/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

BW Workshop Services Pte Ltd (HQ)
 291 Kaki Bukit Avenue 1, Shun Li Industrial Park
 Singapore 416080

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Jun 2021)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFS1866R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR (RH)	Distorted	860.40 FL	*860.40 FL
2	2		*REAR DOOR HINGE (RH)	Not Necessary	162.40 FL	*- FL
3	1		*REAR DOOR CHECKER (RH)	Not Necessary	110.50 FL	*- FL
4	1		*REAR DOOR STICKER (SET) (RH)	Necessary	56.00 FL	*56.00 FL
5	1		*REAR DOOR TRIM (RH)	Not Necessary	1,075.00 FL	*- FL
6	1		*REAR DOOR HANDLE (RH)	Cut	117.60 FL	*117.60 FL
7	1		*REAR DOOR STRIKER (RH)	Not Necessary	58.50 FL	*- FL
8	1		*REAR DOOR LOCK (RH)	Damaged	243.10 FL	*243.10 FL
9	1		*REAR DOOR MOLDING (RH)	Deformed	81.20 FL	*81.20 FL
10	1		*REAR DOOR GLASS MOLDING (RH)	Not Necessary	82.80 FL	*- FL
11	1		*REAR POWER WINDOW MOTOR (RH)	Damaged	214.50 FL	*214.50 FL
12	1		*REAR FENDER (RH)	Dented	684.00 FL	*684.00 FL
13	1		*FRONT DOOR (RH) (NPA)	Repair	0.00 FL	*- FL
14	1		*REAR WINDOW SASH (RH)	Necessary	124.00 FL	*124.00 FL
15	1		*DOOR GLASS CHANNEL (RH)	Bent	80.00 FL	*80.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,950.00	2,460.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	790.00	492.16
Total Parts (\$\$)	3,160.00	1,968.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIT AND TO RENEW AFFECTED PARTS	New	1,000.00	700.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	750.00	600.00
3	TO REMOVE AND REFIT DOOR GLASS	New	100.00	80.00
4	TO REMOVE AND REFIT REAR FENDER GLASS	New	100.00	60.00
5	TO REMOVE DOORS FITTINGS	New	120.00	80.00
Gross Labour Cost (S\$)			2,070.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >