

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003477/T1PA3Q2
Date: 25/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070132973
Claimant Vehicle No :	SHD4089C	Insured Vehicle No :	SMV1383T
Date of Loss:	16/03/2021	Nature of Claim:	TP
		Claim No:	3893089118SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4089C	Engine No:	G4LEKU400874
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU187739
Reg. Date:	30/10/2019 (Man. Year: 2019)	Odometer:	118928 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,136.52	677.24	1,459.28	68.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,310.00	300.00	18.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,746.52	1,987.24	1,759.28	46.96
+ GST 7.00/7.00% (S\$)	262.26	139.11	123.15	46.96

Nett Amount (S\$)	4,008.78	2,126.35	1,882.43	46.96
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
(S\$)		2,651.92		
Liabe Amount (50.00%) (S\$)		1,325.96		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,327.96		
Global Sum Settlement (S\$)		1,330.00		

INSPECTION

Date of Assignment: 17/03/2021

Date Inspected: 17/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -RR BUMPER	Deformed	459.40 FL	*459.40 FL
2	10		*BUMPER COVER CLIP REAR	Necessary	22.00 FL	*22.00 FL
3	1		*BRACKET ASSY -RR BUMPER SI	Not Necessary	55.80 FL	*- FL
4	1		*PANEL ASSY -QUARTER OUTER	Repair	1,768.30 FL	*- FL
5	1		*FUEL TANK LID (PETROL ONL)	Necessary	15.00 FS	*15.00 FS
6	1		*CAP ASSY -WHEEL HUB	Cut	346.40 FL	*346.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,666.90	842.80
- List Item Discount on L Items 20.00/20.00% (\$)	530.38	165.56
Total Parts (\$)	2,136.52	677.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	900.00	700.00
2	SPRAYPAINT ON AFFECTED AREA	New	550.00	500.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
4	ADJUST REAR WHEEL ALIGNMENT	New	80.00	80.00
Gross Labour Cost (\$\$)			1,610.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >