



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBC 7662D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FENDER (CONSISTENT)	CRACKED	85.00	85.00
2	FORK INNER TUBES (CONSISTENT)	SERVICEABLE	290.00	-
2	FORK OUTER TUBES (CONSISTENT)	SERVICEABLE	250.00	-
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	185.00	-
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	135.00	-
1	FRONT RIM SHAFT (CONSISTENT)	NOT NECESSARY	45.00	-
1	FRONT RIM BEARING (CONSISTENT)	NOT NECESSARY	38.00	-
1	FRONT WHEEL RIM (CONSISTENT)	SERVICEABLE	320.00	-
1	TOP COWLING (CONSISTENT)	TO REPAIR SEE LABOUR	135.00	-
1	WINDSHIELD (CONSISTENT)	NOT NECESSARY	85.00	-
1	HEADLAMP (CONSISTENT)	SCRATCHED	185.00	185.00
2	FRONT SIGNALS (CONSISTENT)	N/S CRACKED	120.00	60.00
1	HANDLE BAR (CONSISTENT)	BENT	95.00	95.00
2	HANDLE BAR END (CONSISTENT)	NOT NECESSARY	50.00	-
1	BRAKE LEVER (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	56.00	-
1	CLUTCH LEVER (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	56.00	-
2	SIDE MIRRORS (CONSISTENT)	BROKEN	110.00	110.00
1	FUEL TANK (CONSISTENT)	NOT NECESSARY	495.00	-
1	EXHAUST ASSY (CONSISTENT)	BENT	585.00	585.00
1	EXHAUST PROTECTOR (CONSISTENT)	BENT	85.00	85.00
1	FRONT FOOTREST -R/H (CONSISTENT)	TORN	35.00	35.00
1	FRONT FOOTREST BRACKET -R/H (CONSISTENT)	BENT	50.00	50.00
1	BRAKE PEDAL (CONSISTENT)	TO REPAIR SEE LABOUR	42.00	-
1	REAR FENDER (CONSISTENT)	DISTORTED	65.00	65.00
1	REAR TAILBOARD (CONSISTENT)	CRACKED	145.00	145.00
1	REAR TAILLAMP (CONSISTENT)	CRACKED	180.00	180.00
1	REAR SIGNAL -R/H (CONSISTENT)	NOT NECESSARY	65.00	-
1	SET CRASH BAR (CONSISTENT)	TO REPAIR SEE LABOUR	150.00	-

Report Ref No. CC4/ASM21003481/Uga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FOOTREST -R/H (CONSISTENT)	DAMAGED	28.00	28.00
1	REAR FOOTREST BRACKET -R/H (CONSISTENT)	NOT NECESSARY	48.00	-
	LESS 10% DISCOUNT		-421.30	-170.80
			3,791.70	1,537.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET NUMBER PLATE (SN) (CONSISTENT)	REAR BENT	28.00	10.00
2	FORK OILS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN) (CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN) (CONSISTENT)	NOT NECESSARY	75.00	-
1	REAR BOX (SN) (CONSISTENT)	SERVICEABLE	380.00	-
1	REAR BOX BRACKET (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	160.00	-
			729.00	10.00
	<b><u>LABOUR</u></b>			
	TO PROVIDE TRANSPORT (LOD).		50.00	50.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING .	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME .	NOT NECESSARY	350.00	-
	TO PROVIDE LABOUR .INCLUSIVE OF THE REPAIR OF TOP COWLING ,BRAKE PEDAL ,SET CRASH BAR AND REAR BOX BRACKET.		400.00	300.00
			880.00	350.00
<b>GRAND TOTAL</b>			<b>5,400.70</b>	<b>1,897.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,300.00</b>

Report Ref No. CC4/ASM21003481/Uga3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.