

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21003495/APS3Q2**Date:** 05/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900236714
Claimant Vehicle No :	SLD1946B	Insured Vehicle No :	SMQ1636R
Date of Loss:	10/02/2021	Nature of Claim:	TP
		Claim No:	5024399273SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD1946B	Engine No:	2ARU327193
Make & Model:	TOYOTA CAMRY, 2.4 (A)	Chassis No:	MR053AK5004011117
Reg. Date:	07/06/2016 (Man. Year: 2016)	Odometer:	124404 km
Colour:	Black		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,235.90	2,032.72	4,203.18	67.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,390.00	1,110.00	44.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,735.90	3,422.72	5,313.18	60.82
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	8,735.90	2,700.00	6,035.90	69.09
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
		(S\$)		
		3,100.00		
Liabe Amount (50.00%) (S\$)		1,550.00		
Global Sum Settlement (S\$)		1,500.00		

INSPECTION

Date of Assignment:	15/03/2021	
Date Inspected:	15/03/2021	Inspected At: Advance Auto Garage 10 Kaki Bukit Road 2, #01-21 First East Centre Singapore 417868
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER	Repair	797.40 F	*- FL
2	1		*FRONT LH DOOR	Dented	1,219.40 F	*1,219.40 FL
3	1		*REAR LH DOOR	Dented	1,293.50 F	*1,293.50 FL
4	1		*REAR LH DOOR WEATHERSTRIPE	Cut	197.40 F	*197.40 FL
5	1		*ROCKER PANEL SIDE SKIRT LH	Repair	565.70 F	*- FL
6	1		*ROCKER PANEL SIDE SKIRT CLIPS	Not Necessary	50.00 FS	*- FS
7	1		*REAR LH WHEEL RIM	Not Necessary	2,112.50 F	*- FL
					Sub Total (S\$)	6,235.90 2,710.30
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00 677.58
					Total Parts (S\$)	6,235.90 2,032.72

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	500.00
2	SPRAY PAINTING	New	1,000.00	700.00
3	WIRING	New	50.00	30.00
4	TO TRANSFER FRONT AND REAR DOOR FITTINGS	New	300.00	160.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (\$)			2,500.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >