

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21003500/EQD3E2

**Date:** 03/08/2021

### REFERENCE

Insured/Claimant:	NEVILLE BERNARD BESTON	Policy No:	2070145945	
Date of Loss:	15/03/2021	Nature of Claim:	OD	Claim No: 8096645066SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV6317C	Engine No:	DEM025294
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF43MN000687
Reg. Date:	12/10/2020 (Man. Year: 2020)	Odometer:	3771 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$137,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,297.00	5,594.56	1,702.44	23.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,772.00	7,022.00	2,750.00	28.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,069.00</b>	<b>12,616.56</b>	<b>4,452.44</b>	<b>26.08</b>
<b>- Excess (S\$)</b>	<b>1,100.00</b>	<b>1,100.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>15,969.00</b>	<b>11,516.56</b>	<b>4,452.44</b>	<b>27.88</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,117.83</b>	<b>806.16</b>	<b>311.67</b>	<b>27.88</b>
<b>Nett Amount (S\$)</b>	<b>17,086.83</b>	<b>12,322.72</b>	<b>4,764.11</b>	<b>27.88</b>

### INSPECTION

Date of Assignment:	17/03/2021		
Date Inspected:	17/03/2021	Inspected At:	24 BENOI SECTOR Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	12.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LOWER REINFORCEMENT BAR - LH	Necessary	49.00 FS	*39.20 FS
2	1		*FLOOR EXTENSION - LH	Dented	141.00 FS	*112.80 FS
3	1		*REAR CONNECTING STRUT FOR FLOOR PLATE	Bent	53.00 FS	*42.32 FS
4	4		*INNER SOCKET HEAD BOLTS - M10X25	Necessary	12.00 FS	*8.96 FS
5	1		*HEAT SHIELD FOR CENTER SILENCER	Bent	137.00 FS	*109.20 FS
6	5		*FLOOR PAN HEAT SHIELD NUT	Not Necessary	7.00 FS	-
7	1		*FUEL TANK	Dented	5,180.00 FS	*4,144.00 FS
8	1		*FUEL PUMP TANK SEAL RING	Necessary	40.00 FS	*31.68 FS
9	1		*HEAT SHIELD FOR FUEL TANK	Bent	186.00 FS	*148.40 FS
10	1		*CENTRE EXHAUST SILENCER	Dented	896.00 FS	*716.40 FS
11	1		*DUAL CLIP FOR EXHAUST SILENCER	Necessary	59.00 FS	*47.12 FS
12	1		*REAR SILENCER DUAL CLIP	Necessary	104.00 FS	*82.88 FS
13	1		*REAR UNDERBODY TRIM - LH	Cut	133.00 FS	*106.00 FS
14	1		*SUNDRIES	Necessary	300.00 FS	*5.60 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (S\$)</b>	<b>7,297.00</b>
						<b>5,594.56</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE AND REINSTALL CENTER CONSOLE TO FACILITATE RENEWAL OF FLOOR PAN	New	1,800.00	1,800.00
2	TO REMOVE AND REINSTALL REAR AND CENTRE EXHAUST SILENCER. TO ALIGN TO POSITION	New	480.00	480.00
3	TO REMOVE AND RENEW FUEL TANK ASSY	New	600.00	600.00
4	TO REMOVE AND REINSTALL FRONT SEAT ASSY, REAR SEAT ASSY, BACK REST, ABCD PILLAR TRIMS, SILL TRIMS AND CARPETS	New	2,400.00	2,400.00
5	TO CUT OUT AND WELD UNDERCARRIAGE FLOOR PAN	New	2,800.00	1,000.00
6	TO RESPRAY UNDERCARRIAGE FLOOR PAN. TO CARRY OUT STONE CHIP TREATMENT, CAVITY PRESERVATION AND JOINT SEALER WORKS	New	1,500.00	550.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>9,772.00</b>	<b>7,022.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >