

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21003504/GVF3E2

**Date:** 19/05/2021

### REFERENCE

|                              |                                      |                             |            |           |              |
|------------------------------|--------------------------------------|-----------------------------|------------|-----------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2070086222 |           |              |
| <b>Claimant Vehicle No :</b> | FBL958A                              | <b>Insured Vehicle No :</b> | SJG5730M   |           |              |
| Date of Loss:                | 16/03/2021                           | Nature of Claim:            | TP         | Claim No: | 0968011235SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>FBL958A</b>                    | Engine No:  | E3N9E007691       |
| Make & Model:               | YAMAHA MW 125 3-WHEELER, 125cc    | Chassis No: | MLESE781111007691 |
| Reg. Date:                  | 26/05/2016 (Man. Year: 2016)      | Odometer:   | 0 km              |
| Colour:                     | Black                             |             |                   |
| Engine Capacity:            | 125 cc                            |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |           |
|-------------------|---------------|------------------|-----------|
| Front Tyre Size:  | 90/80-14      | Rear Tyre Size:  | 110/90-12 |
| Front Left Side:  | Michelin 4 mm | Rear Left Side:  | IRC 4 mm  |
| Front Right Side: | 0 mm          | Rear Right Side: | 0 mm      |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

|                             |            |               |   |
|-----------------------------|------------|---------------|---|
| Date of Assignment:         | 17/03/2021 |               |   |
| Date Inspected:             | 18/03/2021 | Inspected At: | BEAR GARAGE (HQ)<br>25 KAKI BUKIT ROAD 4 #03-62<br>Singapore 417800 |
| Estimated Period of Repair: | 5.0 days   |               |   |

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$7,500.00

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                    | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------|-----------|------------|--------|
| 1   | 2   |          | *FRONT RIM                     | * Check   | 0.00 F     | *- F   |
| 2   | 1   |          | *FRONT FORK ASSY               | * Check   | 0.00 F     | *- F   |
| 3   | 1   |          | *FRONT HEADLAMP                | * Check   | 0.00 F     | *- F   |
| 4   | 1   |          | *FRONT LH SIGNAL LAMP          | Cut       | 0.00 F     | *- F   |
| 5   | 1   |          | *HANDLE BAR                    | Bent      | 0.00 F     | *- F   |
| 6   | 1   |          | *HANDLE BAR GRIP               | Necessary | 0.00 F     | *- F   |
| 7   | 1   |          | *HANDLE BAR BALANCER RH        | Cut       | 0.00 F     | *- F   |
| 8   | 1   |          | *HAND BRAKE LEVER LH           | Bent      | 0.00 F     | *- F   |
| 9   | 1   |          | *SIDE FAIRING LH               | Cut       | 0.00 F     | *- F   |
| 10  | 1   |          | *SIDE FAIRING TOP GARNISH      | Cut       | 0.00 F     | *- F   |
| 11  | 1   |          | *SIDE FAIRING INNER GARNISH LH | Cracked   | 0.00 F     | *- F   |
| 12  | 1   |          | *REAR FAIRING RH               | Cut       | 0.00 F     | *- F   |
| 13  | 1   |          | *RH STEP BOARD                 | Cut       | 0.00 F     | *- F   |
| 14  | 1   |          | *RH STEP BOARD GARNISH         | Cracked   | 0.00 F     | *- F   |
| 15  | 1   |          | *RH REAR FAIRING GARNISH       | Dented    | 0.00 F     | *- F   |
| 16  | 1   |          | *RH REAR COVER                 | Cracked   | 0.00 F     | *- F   |
| 17  | 1   |          | *LH HAND LEVER PROTECTOR       | Cracked   | 0.00 F     | *- F   |
| 18  | 1   |          | *MAIN STAND                    | Cut       | 0.00 F     | *- F   |
| 19  | 1   |          | *EXHAUST MUFFLER HEAT SHIELD   | Dented    | 0.00 F     | *- F   |
| 20  | 1   |          | *EXHAUST MUFFLER ASSY          | * Check   | 0.00 F     | *- F   |
| 21  | 1   |          | *SWING ARM                     | * Check   | 0.00 F     | *- F   |
| 22  | 1   |          | *REAR SUB FRAME                | * Check   | 0.00 F     | *- F   |
| 23  | 1   |          | *STICKER                       | Necessary | 0.00 F     | *- F   |
| 24  | 1   |          | *TRANSMISSION COVER            | Cut       | 0.00 F     | *- F   |
| 25  | 1   |          | *DRIVE SHAFT COVER             | Cut       | 0.00 F     | *- F   |
| 26  | 1   |          | *FRT LH WHEEL GUARD            | Cut       | 0.00 F     | *- F   |

F=Franchise part.

|                   |      |      |
|-------------------|------|------|
| Total Parts (S\$) | 0.00 | 0.00 |
|-------------------|------|------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >