

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21003506/QEA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100383394
<b>Claimant Vehicle No :</b>	SHB5851Y	<b>Insured Vehicle No :</b>	SKP3051T
Date of Loss:	11/03/2021	Nature of Claim:	TP
		Claim No:	0783092682SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB5851Y</b>		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR6560060
Reg. Date:	22/01/2016 (Man. Year: 2015)	Chassis No:	JTDKN36U905766897
Colour:	Maroon	Odometer:	836716 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Neuton 6 mm	Rear Left Side:	Neuton 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Neuton 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,367.58	1,001.96	5,365.62	84.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,163.00	520.00	1,643.00	75.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,530.58</b>	<b>1,521.96</b>	<b>7,008.62</b>	<b>82.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,530.58</b>	<b>1,400.00</b>	<b>7,130.58</b>	<b>83.59</b>
<b>+ Car Rental (5.0 x S\$103.79/day) (S\$)</b>		518.95		
		<b>(S\$)</b>	1,918.95	
<b>Liabe Amount (50.00%) (S\$)</b>		<b>959.48</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>966.48</b>		

INSPECTION

Date of Assignment:	12/03/2021	
Date Inspected:	12/03/2021	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

**Adjuster:** OI SUN PIN**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	21.00 F	*15.75 F
2	1		*BUMPER REAR (DISC 25%)	Crumpled	458.60 F	*343.95 F
3	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Broken	94.80 F	*71.10 F
4	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Bent	205.70 F	*154.28 F
5	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
6	1		*ADVERTISEMENT STICKER (SN)	Necessary	296.88 F	*296.88 F
7	1		*FENDER RR/LH	Serviceable	766.80 F	*- F
8	1		*STICKER DECAL 6555 8888	Serviceable	21.60 F	*- F
9	1		*FENDER LINER R/LH	Serviceable	141.30 F	*- F
10	1		*SMRT LOGO	Serviceable	7.80 F	*- F
11	1		*TAIL LAMP LH	Serviceable	548.40 F	*- F
12	1		*TAIL LAMP RH	Serviceable	557.80 F	*- F
13	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
14	1		*END PANEL	Serviceable	602.10 F	*- F
15	1		*UNDER COVER RR SHIELD	Serviceable	63.90 F	*- F
16	1		*UNDER COVER SUB-ASSY ,RR FLOOR	Serviceable	514.50 F	*- F
17	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
18	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
19	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
20	1		*BUMPER SEAL ,RR RH	Serviceable	65.70 F	*- F
21	1		*BUMPER SEAL RR LH	Serviceable	88.90 F	*- F
22	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
23	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
24	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
25	1		*ANTENNA ,ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
26	1		*ARM SUB-ASSY ,RR BUMPER LH	Serviceable	139.60 F	*- F
27	1		*ARM SUB-ASSY ,RR BUMPER RH	Serviceable	139.60 F	*- F
28	1		*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F
29	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
30	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>6,367.58</b>	<b>1,001.96</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	507.00	200.00
2	SPRAY PAINT	New	1,296.00	300.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
6	TO WASH AND VACUUM	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,163.00</b>	<b>520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >