



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 961K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,045.00	-
1	FRONT BONNET HIAGE RH	TO REPAIR SEE LABOUR	137.50	-
1	FRONT BONNET HIAGE LH	TO REPAIR SEE LABOUR	137.50	-
1	FRONT BUMPER	BUCKLED	1,140.00	1,109.00
1	FRONT HEADLAMP RH	CUT	1,078.00	1,078.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	649.00	-
1	FRONT HEADLAMP BRACKET RH (TOP PANAL)	TO REPAIR SEE LABOUR	61.00	-
1	FRONT BUMPER BRACKET RH	SERVICEABLE	53.00	-
1	FRONT FOG LAMP COVER RH	DENTED	104.00	104.00
1	FRONT FOG LAMP RH	SERVICEABLE	245.00	-
1	FRONT SPORT RIM RH	SERVICEABLE	1,473.00	-
1	FRONT TYRE RH	SERVICEABLE	225.00	-
1	FRONT KNUCKER ARM RH	SERVICEABLE	758.00	-
1	FRONT WHEEL HUP RH	SERVICEABLE	589.00	-
1	FRONT WHEEL BEARING RH	SERVICEABLE	280.00	-
1	FRONT LOWER ARM RH	SERVICEABLE	487.00	-
1	FRONT ABSORBER RH	SERVICEABLE	484.00	-
1	FRONT TIE ROD RH	SERVICEABLE	166.00	-
1	FRONT TIE ROD INNER RH	SERVICEABLE	122.00	-
1	FRONT TORSION BAR LINK RH	SERVICEABLE	125.00	-
1	FRONT DRIVE SHAFT ASSY RH	TO REPAIR SEE LABOUR	2,676.00	-
	LESS 10% DISCOUNT		-	-229.10
			12,035.00	2,061.90
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING AND SYSTEM FUNCTION.		120.00	20.00
	TO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX UNDERCARRIAGE.	NOT NECESSARY	600.00	-

Report Ref No. CS/UOI21003510/Kqd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY ACCIDENT FRONT PORTION.		1,000.00	400.00
	TO KNOCKING AND WELDING FRONT PORTION. INCLUSIVE OF THE REPAIR OF FRONT BONNET, FRONT BONNET HIAGE RH, FRONT BONNET HIAGE LH, FRONT FENDER RH, FRONT HEADLAMP BRACKET RH (TOP PANAL) AND FRONT DRIVE SHAFT ASSY RH.		1,000.00	300.00
	TO APPLY RUST PROOFING TO AFFECTED AREA.	NOT NECESSARY	150.00	-
	TO REPLACE FRONT TYRE.	NOT NECESSARY	55.00	-
	TO CHECK FOR FUNCTION AND ALIGNMENT HEADLAMP.	NOT NECESSARY	80.00	-
	TO CONDUCT RE-PROGRAMME AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE.	NOT NECESSARY	150.00	-
			3,275.00	720.00
<b>GRAND TOTAL</b>			<b>15,310.00</b>	<b>2,781.90</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,200.00</b>

Report Ref No. CS/UOI21003510/Kqd3e2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.