

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21003514/DRS3Q2  
**Date:** 27/09/2021**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1900090400   |
| <b>Claimant Vehicle No :</b> | SLM9880G                             | <b>Insured Vehicle No :</b> | SMK7968A     |
| Date of Loss:                | 08/03/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 2237280206SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                      |             |                   |
|-----------------------------|--------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLM9880G</b>                      |             |                   |
| Make & Model:               | MAZDA 3, 1.5 HATCHBACK L SP.6EAT (A) | Engine No:  | P520442049        |
| Reg. Date:                  | 19/04/2017 (Man. Year: 2017)         | Chassis No: | JM6BN22A8H0150351 |
| Colour:                     | Grey                                 | Odometer:   | 124190 km         |
| Engine Capacity:            | 1496 cc                              |             |                   |
| Market Value/New Car Price: | N/A                                  |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>    |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 205/60 R16   | Rear Tyre Size:  | 205/60 R16   |
| Front Left Side:  | Pirelli 5 mm | Rear Left Side:  | Pirelli 5 mm |
| Front Right Side: | Pirelli 5 mm | Rear Right Side: | Pirelli 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 8,195.20          | 1,799.84          | 6,395.36          | 78.04         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 5,400.00          | 960.00            | 4,440.00          | 82.22         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>13,595.20</b>  | <b>2,759.84</b>   | <b>10,835.36</b>  | <b>79.70</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>2,200.00</b>   |                   |               |

|                                                 |                  |                 |                  |              |
|-------------------------------------------------|------------------|-----------------|------------------|--------------|
| (S\$)                                           | 13,595.20        | 2,200.00        | 11,395.20        | 83.82        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 951.66           | 154.00          | 797.66           | 83.82        |
| <b>Nett Amount (S\$)</b>                        | <b>14,546.86</b> | <b>2,354.00</b> | <b>12,192.86</b> | <b>83.82</b> |
| <b>+ Car Rental (6.0 x S\$100.00/day) (S\$)</b> |                  | 600.00          |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 36.45           |                  |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>2,990.45</b> |                  |              |

INSPECTION

Date of Assignment: 18/03/2021

Date Inspected: 18/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

JWG International Pte Ltd (HQ)  
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint  
 Singapore 568047

**Adjuster:** BRYAN TANI**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT DOOR RH                        | Bent          | 1,826.00 FL | *1,200.40 FL |
| 2   | 1   |          | *FRONT DOOR WINDOW MOULDING RH        | Not Necessary | 312.00 FL   | *- FL        |
| 3   | 1   |          | *FRONT DOOR CHROME MOULDING RH        | Not Necessary | 331.00 FL   | *- FL        |
| 4   | 1   |          | *FRONT DOOR BLACK PLASTIC MOULDING RH | Not Necessary | 191.00 FL   | *- FL        |
| 5   | 2   |          | *FRONT DOOR HINGE LH                  | Not Necessary | 186.00 FL   | *- FL        |
| 6   | 1   |          | *FRONT DOOR WEATHERSTRIP RH           | Not Necessary | 131.00 FL   | *- FL        |
| 7   | 1   |          | *FRONT DOOR HANDLE RH                 | Not Necessary | 678.00 FL   | *- FL        |
| 8   | 1   |          | *FRONT DOOR INNER TRIM BOARD RH       | Not Necessary | 673.00 FL   | *- FL        |
| 9   | 1   |          | *REAR DOOR RH                         | Bent / Dented | 1,984.00 FL | *1,049.40 FL |
| 10  | 1   |          | *REAR DOOR WINDOW MOULDING RH         | Not Necessary | 312.00 FL   | *- FL        |
| 11  | 1   |          | *REAR DOOR CHROME MOULDING RH         | Not Necessary | 331.00 FL   | *- FL        |
| 12  | 1   |          | *REAR DOOR BLACK PLASTIC MOULDING RH  | Serviceable   | 191.00 FL   | *- FL        |
| 13  | 2   |          | *REAR DOOR HINGE LH                   | Not Necessary | 186.00 FL   | *- FL        |
| 14  | 1   |          | *REAR DOOR WEATHER STRIP RH           | Serviceable   | 151.00 FL   | *- FL        |
| 15  | 1   |          | *REAR DOOR HANDLE RH                  | Not Necessary | 295.00 FL   | *- FL        |
| 16  | 1   |          | *REAR DOOR INNER TRIM BOARD RH        | Not Necessary | 673.00 FL   | *- FL        |
| 17  | 1   |          | *ROCKER PANEL RH                      | Not Necessary | 1,193.00 FL | *- FL        |
| 18  | 1   |          | *DOOR EDGE PROTECTOR                  | Serviceable   | 300.00 FS   | *- FS        |
| 19  | 1   |          | *FRONT DOOR INNER TRIM CLIPS          | Not Necessary | 50.00 FS    | *- FS        |
| 20  | 1   |          | *REAR DOOR INNER TRIM CLIPS           | Not Necessary | 50.00 FS    | *- FS        |
| 21  | 1   |          | *ROCKER PANEL SEALANT                 | Not Necessary | 80.00 FS    | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>10,124.00</b> | <b>2,249.80</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 1,928.80         | 449.96          |
| <b>Total Parts (\$\$)</b>                                  | <b>8,195.20</b>  | <b>1,799.84</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                         | Lab.Type | Repairer's      | Amount        |
|---------------------------------|-----------------------------------------------------------------------------------------------------|----------|-----------------|---------------|
| <b><u>Labour Items</u></b>      |                                                                                                     |          |                 |               |
| 1                               | TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS                                       | New      | 300.00          | 0.00          |
| 2                               | TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS                                             | New      | 2,000.00        | 400.00        |
| 3                               | TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS                                                      | New      | 2,000.00        | 400.00        |
| 4                               | TO TUFF COAT DAMAGED AREAS                                                                          | New      | 200.00          | 40.00         |
| 5                               | TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS                                                   | New      | 200.00          | 60.00         |
| 6                               | TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS                                                    | New      | 200.00          | 60.00         |
| 7                               | TO CHECK & REFIX ALL ELECTRICAL WIRINGS                                                             | New      | 200.00          | 0.00          |
| 8                               | TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS | New      | 300.00          | 0.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                     |          | <b>5,400.00</b> | <b>960.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >