

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003515/KPA3Q2**Date:** 24/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993682
Claimant Vehicle No :	SGS5856G	Insured Vehicle No :	YP6596C
Date of Loss:	08/03/2021	Nature of Claim:	TP
		Claim No:	2410460923SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS5856G	Engine No:	1ZZ2811486
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	ZNE100348956
Reg. Date:	19/03/2007 (Man. Year: 2006)	Odometer:	138687 km
Colour:	Metallic Blue		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,552.17	1,254.67	1,297.50	50.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	610.00	350.00	36.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,512.17	1,864.67	1,647.50	46.91
Approved Total (Overridden) (S\$)		1,450.00		
Nett Amount (S\$)	3,512.17	1,450.00	2,062.17	58.71
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	18/03/2021	Hwa Seng Spray Painting Co (160 SIN MING)
Date Inspected:	22/03/2021 Inspected At:	160 SIN MING DRIVE, #05-11 SIN MING
		AUTOCITY
		Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S/F DOOR	Bent	1,253.80 FL	*1,205.10 FL
2	1		*O/S/F DOOR WING MIRROR	Cracked	1,022.60 FL	*391.00 FL
3	1		*O/S/F HANDLE	Dented	76.80 FL	*76.80 FL
4	1		*O/S/F DOOR OUTER MOULDING	Serviceable	86.20 FL	*- FL
5	1		*O/S/F DOOR LOCK	Repair	78.30 FL	*- FL
6	1		*O/S/F POWER WINDOW MOTOR	Serviceable	679.10 FL	*- FL
7	1		*O/S/F POWER WINDOW REGULATOR	Repair	206.10 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,402.90	1,672.90
- List Item Discount on L Items 25.00/25.00% (S\$)	850.73	418.23
Total Parts (S\$)	2,552.17	1,254.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL KNOCKING	New	350.00	250.00
2	SPRAY PAINTING	New	450.00	300.00
3	WIRE CHECKING (NPA)	New	0.00	0.00
4	LABOUR TO TRANSFER THE DOOR PARTS & ATTACHMENT	New	160.00	60.00
Gross Labour Cost (\$\$)			960.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >