

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile								
AXA	NSURANCE PTE		Ref: CC4/ASM18005301/T1hb3q2					
		. 2.12						
	ENTON WAY #24		Date :	16-05-2019				
AXA TOWERSINGAPORE 068811								
	I:STACEY NG		Code :	ASM				
1.	1. Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	SKV 6745Z	Veh. In	nspected	SFY 3880D			
	Policy No.	GA269131	Covera	age (\$)	0.00			
	Claim No.	S8M00BDM	Exces	s (\$)	0.00			
	Assign From		Assigr	n Date	21/03/2018			
2.		Vehicle Partic	ulars &	Condition				
	Make & Model	B.M.W. 740LI	c.c		2979			
	Engine No.	HIDDEN	Year o	f Reg.	2014			
	Chassis No.	WBAYE42040DD87413	Colour	r	BLACK			
	Odometer	41694	Steerin	ng	IN ORDER			
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM			
	General	GOOD						
3.		Condition	ons of 1	Гyres				
		Size	Make		Balance			
	R/H Front Tyre	275/40 R19	GOODY	YEAR	6 mm			
	L/H Front Tyre	275/40 R19	GOODY	YEAR	6 mm			
	R/H Rear Tyre	275/40 R19	GOODY	YEAR	6 mm			
	L/H Rear Tyre	275/40 R19	GOODY	YEAR	6 mm			
4.		Description	n of Da	amages				
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR POR	TION.				
	DAMAGES SEE D	ETAILS.						
5.		General	Inform	ation				
	Accident Date	20/03/2018	Inspec	tion Date	21/03/2018			
	Survey held at PERFORMANCE MOTORS LTD							
		303 ALEXANDRA ROAD SINGAPORE 159941						
5a.			marks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	b. Estimate Days of Repair							
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days							



LKK Auto Consultants Pte I 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFY 3880D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN) (CONSISTENT)	* CHECK	80.00	-
1	RR BUMPER LH MOUNT (SN) (CONSISTENT)	* CHECK	198.30	-
1	RR BUMPER RH MOUNT (SN) (CONSISTENT)	* CHECK	198.30	-
1	RR BUMPER LOWER TRIM (PRIMED) (SN) (CONSISTENT)	DEFORMED	224.45	224.45
1	RR BUMPER CTR GUIDE (SN) (CONSISTENT)	* CHECK	51.50	-
1	ADAPTER (SN) (CONSISTENT)	* CHECK	81.00	-
1	RR BUMPER CARRIER (SN) (CONSISTENT)	* CHECK	800.80	-
1	RR BUMPER PANEL PRIMED (SN) (CONSISTENT)	DEFORMED	1,496.35	1,496.35
1	COVER TOW FITTING REAR PRIMED (SN) (CONSISTENT)	* CHECK	50.65	-
1	MODEL LETTERING 740LI (SN) (CONSISTENT)	NECESSARY	62.55	62.55
4	DECOUPLING RING PDC TORQUE CONVERTE (SN) (CONSISTENT)	NECESSARY	20.20	20.20
2	BUMPER PDC SENSOR (A90 SOPHISTOGRAU) (SN) (CONSISTENT)	* CHECK	737.60	-
			4,001.70	1,803.55
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT.		2,550.00	1,700.00
	TO PAINT REAR BUMPER AND BOOTLID.		2,076.00	1,868.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION .		177.00	150.00
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.		271.00	230.00
			-	-
			5,074.00	3,948.00
	GRAND TOTAL		9,075.70	5,751.55

Report Ref No. CC4/ASM18005301/T1hb3q2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		5,751.65
(REPAIR COST NOT CONCLUDE)		·
(EXCLUDE CHECK ITEMS S\$2,198.15 NETT)		

Report Ref No. CC4/ASM18005301/T1hb3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

**Automotive Assessor** 

ATAI, AMSAE-A

HO LEONG CHUAN

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.




51 Ubi Ave 1#01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### PHOTOGRAPHS FOR VEHICLE NO. SFY 3880D

#### INSPECTION











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315












51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315












51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

