



Your Ref: 21.28575

Date: 24<sup>th</sup> Sep 2021

Our Ref: CC4/ASM18005301/T1ps3q2-1

**M/s Axa Insurance Pte Ltd**

C/o: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SFY 3880D**

**INSURED VEHICLE: SKV 6745Z**

**ACCIDENT DATE: 20/03/2018**

We thank you for your instruction on 23/07/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SFY 3880D from M/s Performance Motors Limited.
- b) Singapore Accident Statement and Police Report of Vehicles SFY 3880D and SKV 6745Z.
- c) Colour damaged vehicle photographs of SFY 3880D.

Pre-Repair Inspection Date : 21/03/2018 at M/s Performance Motors Ltd, 303 Alexandra Road, Singapore 159941.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

|                      |                                      |
|----------------------|--------------------------------------|
| Registration Number  | : SFY 3880D                          |
| Make & Model         | : B.M.W. 740LI AT SR LED DSC NAV HUD |
| Year of Registration | : 2014                               |
| Chassis Number       | : WBAYE42040DD87413                  |
| Engine Capacity      | : 2979 cc                            |

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.