



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 6834T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	DENTED / BUCKLED	950.00	950.00
1	FRONT BUMPER	TORN	762.00	461.00
1	FRONT BUMPER LHS RETAINER	NOT NECESSARY	78.00	-
1	FRONT FENDER LHS	TO REPAIR SEE LABOUR	559.00	-
1	FRONT FENDER INNER SHIELD LHS	NOT NECESSARY	151.00	-
1	HEADLAMP LHS	CRACKED	694.00	581.00
1	HEADLAMP BRACKET LHS	NOT NECESSARY	95.00	-
1	LHS FRONT SHOCK ABSORBER	NOT NECESSARY	492.00	-
1	LHS FRONT LOWER ARM	NOT NECESSARY	388.00	-
1	LHS FRONT KNUCKLE ARM	NOT NECESSARY	398.00	-
1	LHS FRONT WHEEL BEARING	NOT NECESSARY	279.00	-
	LESS 20% DISCOUNT		-969.20	-398.40
			3,876.80	1,593.60
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	45.00
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	40.00	-
1	LHS FRONT RIM (SN)	NOT NECESSARY	850.00	-
			950.00	45.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS,REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER LHS.		1,400.00	300.00
	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS.		1,200.00	580.00
	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER ELECTRICAL FUNCTION.		150.00	20.00
	TO REMOVE AND REPLACE REAR RIM.	NOT NECESSARY	100.00	-
	TO REMOVE AND REPLACE FRONT LHS UNDERCARRIAGE.	NOT NECESSARY	140.00	-

Report Ref No. CS/SMO21003535/Utf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		120.00	30.00
			3,110.00	930.00
GRAND TOTAL			7,936.80	2,568.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/SMO21003535/Utf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.