

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC21003536/R1qd3e2
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	30/03/2021
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YP 4579R	Veh. Inspected	l	GBB 7161M
	Policy No.	Z/20/VC00/108728	Coverage (\$)		0.00
	Claim No.	20/21/21/VC00/024339	Excess (\$)		0.00
	Assign From	KENNY LIM	Assign Date		17/03/2021
2.	Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150 M	c.c		2982
	Engine No.	HIDDEN	Year of Reg.		2010
	Chassis No.	JTFAT35Y20K201003	Colour		GREY
	Odometer	349071 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	FAIR			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	195 R15C	BRIDGESTONE		7 mm
	L/H Front Tyre	195 R15C	BRIDGESTONE		7 mm
	R/H Rear Tyre	155 R12C (D)	BRIDGESTONE		5/5 mm
	L/H Rear Tyre	155 R12C (D)	BRIDGESTONE		5/5 mm
4.	Description of Damages				
	THE VEHICLE SUS PORTION.	STAINED DAMAGES AT THE FRONT AND REAR			
5.	General Information				
	Accident Date	15/03/2021	Inspect Date /	Time	18/03/2021 (02:54 PM)
	Survey held at	EMPIRE IMAGE			
		NO.4 PANDAN LOOP (BLK K / BLK 1) SINGAPORE 128222			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC21003536/R1qd3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser