

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21003537/T1QF3E2

**Date:** 16/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800075913  
**Claimant Vehicle No :** FBS1276R **Insured Vehicle No :** SJM7375K  
Date of Loss: 11/03/2021 Nature of Claim: TP Claim No: 6594636268SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBS1276R**  
Make & Model: HONDA ADV150, 149cc ABS CVT Engine No: KF61E1031371  
Reg. Date: 21/01/2021 (Man. Year: 2020) Chassis No: MH1KF6118LK031419  
Colour: Silver Odometer: 0 km  
Engine Capacity: 149 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 110/80 R14 Rear Tyre Size: 130/70 R13  
Front Left Side: Federal 5 mm Rear Left Side: Federal 5 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 17/03/2021  
Date Inspected: 23/03/2021 Inspected At: Bikes and Tea Pte Ltd (HQ)  
25 Kaki Bukit Road 4 #01-43, Synergy@KB  
Singapore 417800  
Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH SIGNAL LAMP	Cut	0.00 F	*- F
2	1		*HANDLE BAR	Bent	0.00 F	*- F
3	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
4	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
5	2		*SIDE FAIRING	Cut	0.00 F	*- F
6	1		*SIDE FAIRING INNER GARNISH	* Check	0.00 F	*- F
7	1		*CENTER GARNISH	Cut	0.00 F	*- F
8	1		*REAR FAIRING	Cut	0.00 F	*- F
9	2		*STEP GARNISH LH & RH	Cut	0.00 F	*- F
10	1		*SIDE STAND	Bent	0.00 F	*- F
11	1		*REAR BOX	Cut	0.00 F	*- F
12	1		*REAR BOX BRACKET	* Check	0.00 F	*- F
13	1		*AIR BOX COVER	Cut	0.00 F	*- F
14	1		*CLUTCH COVER	Cut	0.00 F	*- F
15	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >