

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG20013023/QVF3E2-1

**Date:** 06/04/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001412585		
<b>Claimant Vehicle No :</b>	GBG1188A	<b>Insured Vehicle No :</b>	YP6385U		
Date of Loss:	23/11/2020	Nature of Claim:	TP	Claim No:	250086

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBG1188A</b>		
Make & Model:	NISSAN NV200, 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M)	Engine No:	K9KC400D056548
Reg. Date:	31/05/2017 (Man. Year: 2016)	Chassis No:	VSKYBAM20Z0141877
Colour:	White	Odometer:	20394 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/70 R14C	Rear Tyre Size:	175/70 R14C
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,929.94	4,738.28	2,191.66	31.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,440.00	1,540.00	51.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,909.94</b>	<b>6,178.28</b>	<b>3,731.66</b>	<b>37.66</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,909.94</b>	<b>5,000.00</b>	<b>4,909.94</b>	<b>49.55</b>

### INSPECTION

Date of Assignment:	25/11/2020		
Date Inspected:	26/11/2020	Inspected At:	Blk 160 Sin Ming Drive #06-10 Repairer : Lian Heng Painter Company (HQ)
Estimated Period of Repair:	6.0 days		

**Adjuster:** OI SUN PIN

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Apr 2021)		
<b>Parts:</b>	N/A	NISSAN NV200 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) (Model not available in database)	
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG1188A)		
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.		

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH SLIDING DOOR	Dented	1,873.20 FL	*1,415.20 FL
2	1		*RH SLIDING DOOR LOCK	Serviceable	256.40 FL	*- FL
3	1		*RH SLIDING DOOR STRIKER	Serviceable	40.60 FL	*- FL
4	1		*RH SLIDING DOOR LOCK ACTUATOR	Serviceable	334.90 FL	*- FL
5	1		*RH SLIDING DOOR LOWER SEAL	Necessary	29.30 FL	*29.30 FL
6	1		*RH SLIDING DOOR RAIL	Scratched	470.10 FL	*289.40 FL
7	1		*RH SLIDING DOOR CENTRE ROLLER	Jammed	174.40 FL	*174.40 FL
8	1		*RH QUARTER PANEL	Dented	2,239.50 FL	*1,650.00 FL
9	1		*RH TAIL LAMP	Cracked	393.10 FL	*393.10 FL
10	1		*RHR SHOCK ABSORBER	Serviceable	241.40 FL	*- FL
11	1		*RHR WHEEL HUB	Jammed	561.10 FL	*305.20 FL
12	1		*RHR WHEEL CAP	Scratched	123.00 FL	*123.00 FL
13	1		*REAR BUMPER	Crumpled	670.90 FL	*670.90 FL
14	1		*REAR BUMPER BRACKET RH	Cracked	58.70 FL	*58.70 FL
15	1		*RH SLIDING DOOR GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
16	1		*SET RH SLIDING DOOR TRIM CLIPS	Necessary	30.00 FS	*20.00 FS
17	1		*SET RHR QUARTER PANEL TRIM	Necessary	30.00 FS	*20.00 FS
18	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*20.00 FS
19	1		*JOINT SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,676.60</b>	<b>5,249.20</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	746.66	510.92
<b>Total Parts (\$\$)</b>	<b>6,929.94</b>	<b>4,738.28</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & TRANSFER RH SLIDING DOOR FITTINGS	New	120.00	80.00
2	TO REMOVE & TRANSFER RH SLIDING DOOR GLASS	New	200.00	60.00
3	TO REMOVE & INSTALL REVERSE SENSOR	New	80.00	50.00
4	CHECK LIGHTINGS & WIRINGS	New	50.00	30.00
5	RENEW RHR UNDERCARRIAGE	New	200.00	0.00
6	CONDUCT WHEEL ALIGNMENT	New	80.00	60.00
7	RUST PROOFING	New	100.00	60.00
8	TO REMOVE AND RENEW DAMAGED PARTS	New	1,500.00	600.00
9	TO PUTTY AND RE-SPRAY ALL DAMAGED PARTS	New	650.00	500.00
<b>Gross Labour Cost (S\$)</b>			<b>2,980.00</b>	<b>1,440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >