

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003546/KGS3Q2
Date: 15/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100449134-05
Claimant Vehicle No :	SKL574S	Insured Vehicle No :	GBE6117H
Date of Loss:	16/03/2021	Nature of Claim:	TP
		Claim No:	8694059424SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL574S		
Make & Model:	TOYOTA HIACE, 3.0 D HIGH ROOF COMMUTER TURBO (A)	Engine No:	1KD2294119
Reg. Date:	26/09/2013 (Man. Year: 2013)	Chassis No:	JTFST22P700016869
Colour:	White	Odometer:	113176 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,251.72	3,151.72	100.00	3.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,435.00	2,300.00	1,135.00	33.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,686.72	5,451.72	1,235.00	18.47
Approved Total (Overridden) (S\$)		4,350.00		

(S\$)	6,686.72	4,350.00	2,336.72	34.95
+ GST 7.00/7.00% (S\$)	468.07	304.50	163.57	34.95
Nett Amount (S\$)	7,154.79	4,654.50	2,500.29	34.95
+ Loss of Use (10.0 x S\$150.00/day) (S\$)		1,500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,156.50		

INSPECTION

Date of Assignment: 18/03/2021

Date Inspected: 18/03/2021

Estimated Period of Repair: 9.0 days

Inspected At:

City Auto Pte Ltd (Sin Ming) (HQ)
 Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est
 Singapore 575643

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH EXTENSTION PANEL (MIDDLE)	Bent	1,454.00 FL	*1,454.00 FL
2	1		*RH EXTENSION PANEL	Bent	75.60 FL	*75.60 FL
3	1		*RH QUARTER PANEL (REAR)	Bent	1,546.90 FL	*1,546.90 FL
4	1		*REAR BUMPER	Cut	430.90 FL	*430.90 FL
5	1		*REAR RH MUDFLAP	Cracked	134.90 FL	*134.90 FL
6	3		*GLASS SEALANT	Necessary	120.00 FS	*120.00 FS
7	1		*STICKER	Necessary	400.00 FS	*300.00 FS
					Sub Total (\$\$)	4,162.30
					- List Item Discount on L Items 25.00/25.00% (\$\$)	910.58
					Total Parts (\$\$)	3,251.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT WHEEL ALIGNMENT	New	75.00	60.00
2	TO REMOVE AND REFIT THREE UNITS OF WINDOW GLASS	New	400.00	300.00
3	TO REMOVE AND REFIT INTERIOR CABINET AND TRIMS	New	400.00	250.00
4	TO SUPPLY PANEL SEALANT AND TO SEAL OFF ALL WELD SPOT SEAMS AND GAPS	New	160.00	90.00
5	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN REFIX AND TO RENEW ACCIDENT PARTS	New	1,700.00	1,000.00
6	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	700.00	600.00
Gross Labour Cost (\$\$)			3,435.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >