

AUTOMOBILE ASSESSMENT REPORT

TO: LMH GRAB
C/O: ALPHA PERFORMANCE SINGAPORE PTE. LTD.
48 TOH GUAN ROAD EAST,
#04-126 ENTERPRISE HUB,
SINGAPORE 608586

Our Reference: 1120/AP706
Date: 30-Nov-2020

ASSESSMENT OF VEHICLE NO. SJN 3238 U

DATE OF LOSS: 10-Nov-2020

We have carried out a physical assessment at **ALPHA PERFORMANCE SINGAPORE PTE. LTD.**,
48 Toh Guan Road East, #04-126 Enterprise Hub, Singapore 608586, according to your instruction
on **16-Nov-2020** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: SJN 3238 U
Make & Model: HONDA JAZZ 1.3L AT
Year of Registration: 2009
Engine Capacity: 1339
Chassis No.: JHMGE68509S209198
Engine No.: L13Z11009196
Colour: BLUE

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front
RH Make/Size/Thread: MICHELIN 185/55 R16 – 70%
LH Make/Size/Thread: MICHELIN 185/55 R16 – 70%


Rear
RH Make/Size/Thread: MICHELIN 185/55 R16 – 70%
LH Make/Size/Thread: MICHELIN 185/55 R16 – 70%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the REAR portion.

5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$8,248.28
Adjusted Amount:	\$6,130.20
Lump Sum:	\$4,900.00
Estimated Repair Days:	8 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. SJN 3238 U

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	REAR TAILGATE	Bent	967.60	967.60
1	REAR TAILGATE 'JAZZ' EMBLEM	Necessary	45.00	45.00
1	REAR TAILGATE 'LOGO' EMBLEM	Necessary	20.00	20.00
2	REAR TAILGATE DAMPER L/R	Bent	218.60	218.60
2	REAR TAILGATE HINGES L/R	Bent	88.00	88.00
1	REAR TAILGATE WINDSCREEN MOULDING	Necessary	70.00	70.00
1	REAR TAILGATE WIPER ARM	Bent	23.30	23.30
1	REAR TAILGATE WIPER MOTOR	Faulty	238.00	238.00
1	REAR TAILGATE OUTER GARNISH	Cracked	114.60	114.60
4	REAR TAILGATE OUTER GARNISH CLIPS	Necessary	26.00	26.00
2	REAR TAILGATE NUMBER PLATE LAMP L/R	Cracked	65.40	65.40
1	REAR TAILGATE OUTER HANDLE	Cracked	56.70	56.70
1	REAR TAILGATE INNER TRIM BOARD	Cracked	96.30	96.30
1	REAR TAILGATE INNER HANDLE	Cracked	14.30	14.30
2	REAR TAILGATE RUBBER GUDIE STOPPER L/R	Bent	21.00	21.00
1	REAR TAILGATE MECHANISM LOCK	Bent	186.20	186.20
1	REAR TAILGATE LOCK STRIKER	Bent	25.70	25.70
1	REAR TAILGATE WEATHER STRIP	Cut	92.30	92.30
2	REAR TAILLAMP L/R	Cracked	412.40	412.40
1	REAR LH FENDER	Repair	613.80	-
2	REAR FENDER INNER TRIM BOARD L/R	Repair	500.00	-
1	REAR BUMPER	Cracked	490.80	490.80
2	REAR BUMPER SIDE RETAINER L/R	Bent	33.00	33.00
1	REAR END PANEL INNER TOP GARNISH	Cracked	60.80	60.80
4	REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	26.00	26.00
1	REAR END PANEL	Bent	265.80	265.80
1	REAR END PANEL TOW HOOK EXTENSION PANEL	Bent	52.30	52.30
1	SPARE TYRE PANEL TOP BOARD COVER	Cracked	183.90	183.90
1	SPARE TYRE PANEL	Repair	737.00	-
1	REAR EXHAUST SILENCER BOX	Repair	446.80	-
			6,191.60	3,894.00
Less 20% discount			1,238.32	778.80
Parts Total:			4,953.28	3,115.20

ASSESSMENT REPORT FOR VEHICLE NO. SJN 3238 U

SPECIAL NETT ITEMS

1	REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00	80.00
1	REAR TAILGATE INNER TRIM BOARD CLIPS - SET	Necessary	30.00	30.00
1	REAR TAILGATE NUMBER PLATE	Bent	25.00	25.00
1	REAR TAILGATE NUMBER PLATE HOLDER	Cracked	50.00	50.00
2	REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	Necessary	60.00	60.00
1	REAR BUMPER CLIPS - SET	Necessary	30.00	30.00
1	REAR BUMPER REVERSE SENSOR - SET	Cracked	350.00	350.00
Special Nett Total :			625.00	625.00

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	140.00	120.00
2	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet.	100.00	80.00
3	To remove, reinstall tailgate windscreen.	150.00	130.00
4	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	900.00
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,200.00	1,100.00
6	To apply anti-rust chemical on repaired and replaced panel.	80.00	60.00
Labour Total :		2,670.00	2,390.00
TOTAL (PARTS & LABOUR) \$		8,248.28	6,130.20

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$4,900.00

(SINGAPORE DOLLARS FOUR THOUSAND NINE HUNDRED ONLY)



Amas Ong
Automobile Assessor

ALPHA PERFORMANCE SINGAPORE PTE. LTD.

CO.REF: 202035804E
NO 48 TOH GUAN ROAD EAST
#04-126 ENTERPRISE HUB
SINGAPORE 608586
DIRECT LINE: 96472568
TEL: 64683096
FAX: 65155434

Attn: Motor Claims Department
Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

Final Bill: APS-01- 3238
Date: 18/12/2020
Vehicle No: SJN3238U
Make & Model: Honda Jazz 1.3
Accident Date: 10/11/2020

S/N	DESCRIPTION	AMOUNT
1	REPAIR COST (LUMPSUM)	\$4,900.00

GRAND TOTAL \$4,900.00

Kindly make payment to : ALPHA PERFORMANCE SINGAPORE PTE. LTD.



ALPHA PERFORMANCE SINGAPORE PTE. LTD.