

ASS. REC. BY: Tan JHREF: C83/SMO21003553/Ti 43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
☒	☒

Bal. or Market Value: 9102K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMW 3623H Yr Regn: 2020, NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Freed c.c. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 8721 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 6B53105095Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 185/65R15R: ✓

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 23/3/21Survey held at Fei Auto.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COR \$5154.22, 6 DAYS

red: 4222.15:45%

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.H. (\$) _____

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

FEI AUTO

25 Kaki Bukit Road 4 #03-33 Synergy@KB Singapore 417800

Tel: 6702 3533

Fax: 6702 3577

Vehicle No: SMW3623H

Model No. Honda Freed

Chassis no. GB71098277

Accident Date : 16.03.2021

Owner : Tay Puey Seng

Date of Estimate : 20.03.2021

Estimate for Accident Vehicle No. SMW3623H

<u>List Items:</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Total Amount</u>
1 Tailgate	1	\$1,324.50	\$1,324.50 <i>bb</i>
2 Tailgate lock	1	\$112.30	\$112.30 <i>bt</i>
3 Tailgate lock catch	1	\$34.00	\$34.00 <i>X</i>
4 Tailgate inner garnish	1	\$344.20	\$344.20 <i>eng</i>
5 Tailgate weatherstrip	1	\$230.50	\$230.50 <i>aut</i>
6 Tailgate trim	1	\$130.00	\$130.00 <i>X</i>
7 Tailgate lower lining	1	\$321.00	\$321.00 <i>X</i>
8 Tailgate emblem "Freed"	1	\$59.00	\$59.00 <i>nei</i>
9 Tailgate emblem "HYBRID"	1	\$82.00	\$82.00 <i>nei</i>
10 Tailgate outer chrome moulding	1	\$375.12	\$375.12 <i>eng</i>
11 Tailgate windscreen glass moulding	1	\$174.50	\$174.50 <i>nei</i>
12 Tailgate wiper motor	1	\$320.00	\$320.00 <i>X</i>
13 Tailgate pull pocket	1	\$27.00	\$27.00 <i>X</i>
14 Rear fender LH	1	\$1,650.00	\$1,650.00 <i>X</i>
15 Rear fender inner garnish LH	1	\$450.00	\$450.00 <i>de</i>
16 Rear fender shield LH	1	\$105.00	\$105.00 <i>de</i>
17 Rear bumper	1	\$1,120.00	\$1,120.00 <i>de</i>
18 Rear bumper reflector RH <i>LH</i>	1	\$65.70	\$65.70 <i>eng</i>
19 Rear bumper bracket RH <i>LH</i>	1	\$45.80	\$45.80 <i>de</i>
20 Rear bumper side retainer top	2	\$32.00	\$64.00 <i>X</i>
21 Rear bumper side retainer bottom	2	\$26.80	\$53.60 <i>X</i>
22 Taillamp RH <i>LH</i>	1	\$680.00	\$680.00 <i>eng</i>
23 Taillamp panel RH <i>LH</i>	1	\$155.60	\$155.60 <i>Ry</i>
24 Rear end panel	1	\$712.50	\$712.50 <i>Ry</i>
25 Rear end panel top garnish	1	\$203.00	\$203.00 <i>de</i>
26 Rear bumper towing cover	1	\$22.50	\$22.50 <i>X</i>
Sub-Total Amount =			\$8,861.82
Less parts-discount = 25%			\$2,215.46
Sub-Total =			<u>\$6,646.37</u>

<u>Special Nett Items</u>	Qty	Unit Price	Total Amount
1 Rear bumper clips	set	\$55.00	\$55.00 30 net
2 Rear end panel top garnish clips	3	\$5.00	\$15.00 10 net
3 Rear windscreen glass sealant	1	\$50.00	\$50.00 net
Reverse sensor \$200 net			
Sub-Total =			\$120.00
Total cost for parts =			\$6,766.37

<u>Labour charges</u>	
1 Panel beating for replace and repair affected parts	\$1,000.00 800
2 Spray painting	\$1,000.00 800
3 Apply putty and anti-corrosion to affected parts.	\$80.00 30
4 Wiring / bulb checking	\$50.00 30
5 R/R reverse sensor	\$80.00 30
6 Transfer tailgate component, remove refit rear windscreen	\$400.00 60
	<u>\$2,610.00</u>

Total parts	=	\$6,766.37
Total labour	=	\$2,610.00
Total Amount	=	\$9,376.37

Tarphin 97445749
 'WP' 23/3/21 elon
 P/P Resurvey before paint
 Tarphin 01/4/21
 06 days - 07 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: