11/9/21, 9:44 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG21003555/KPA3Q2

Date:

09/11/2021

REFERENCE

Date of Loss:

Reg. Date:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

2100411919

Claimant Vehicle No:

SMM3855H 09/03/2021

Insured Vehicle No:

Nature of Claim:

SKS7786P ΤP

Claim No:

8200882474SG

JTDKB3FUX03083546

2ZR2C54599

181085 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM3855H

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

27/06/2019 (Man. Year: 2018)

Colour: Metallic Red

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: Rear Left Side:

195/65 R15 Sailun 9 mm

Front Left Side: Sailun 9 mm Front Right Side: Sailun 9 mm

Rear Right Side:

Sailun 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------|------------|------------|------------|--------|
| Parts | | 7,659.72 | 364.20 | 7,295.52 | 95.25 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 9,990.00 | 370.00 | 9,620.00 | 96.30 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Gross Total (S\$) | 17,649.72 | 734.20 | 16,915.52 | 95.84 |
| | + GST 7.00/7.00% (S\$) | 1,235.48 | 51.39 | 1,184.09 | 95.84 |

Nett Amount (S\$) 18,885.20 785.59 18,099.61 95.84

0.00

Global Sum Settlement (S\$)

INSPECTION

Date of Assignment: 15/03/2021

Trans-cab Auto Services Pte Ltd Date Inspected: Inspected At: No 2 Ang Mo Kio Street 63 15/03/2021

Singapore 569111

Estimated Period of Repair: 1.5 days

Adjuster: KENNETH KONG Manager: **CHEW HSIAO TONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty Part No. | Particulars | Condition | Repairer's | Amount |
|------|-------------------------|---------------------------------------|--|-------------|------------|
| 1 | 1 | *COVER ,FRONT BUMPER | Repair | 516.00 FL | *- FL |
| 2 | 1 | *REINFORCEMENT SUB-ASSY ,FRONT BUMPER | Repair | 716.60 FL | *- FL |
| 3 | 1 | *ABSORBER ,FRONT BUMPER ENERGY | Cracked | 79.60 FL | *79.60 FL |
| 4 | 1 | *BRACKET ,FRONT BUMPER SIDE ,LH | Serviceable | 59.30 FL | *- FL |
| 5 | 1 | *BRACKET ,FRONT BUMPER SIDE ,RH | Serviceable | 59.30 FL | *- FL |
| 6 | 1 | *COVER ,ENGINE UNDER ,NO.1 | Serviceable | 472.40 FL | *- FL |
| 7 | 1 | *UNIT ASSY ,HEADLAMP LH | Serviceable | 2,637.60 FL | *- FL |
| 8 | 1 | *COMPUTER SUB-ASSY ,HEADLAMP ,LH NO.1 | Serviceable | 960.50 FL | *-FL |
| 9 | 1 | *UNIT ASSY ,HEADLAMP RH | Serviceable | 2,637.60 FL | *- FL |
| 10 | 1 | *COMPUTER SUB-ASSY ,HEADLAMP ,RH NO.1 | Serviceable | 960.50 FL | *-FL |
| 11 | 1 | *GRILLE SUB-ASSY ,RADIATOR | Distorted | 346.00 FL | *346.00 FL |
| 12 | 1 | *GRILLE ,RADIATOR ,LOWER NO.1 | Serviceable | 170.10 FL | *- FL |
| 13 | 1 | *EMBLEM ASSY ,RADIATOR GRILLE | Serviceable | 90.80 FL | *- FL |
| 14 | 1 | *SET BUMPER CLIP FRT | Not Necessary | 95.00 FS | *-FS |
| 15 | 1 | *FRONT NUMBER PLATE WITH MOULDING | Dented | 200.00 FS | *45.00 FS |
| 16 | 1 | *SET FRONT BUMPER RETAINER CLIP | Not Necessary | 85.00 FS | *-FS |
| F=Fr | anchise part. S=SpcNett | L=ListItemDisc. | | | |
| | | | Sub Total (S\$) | 10,086.30 | 470.60 |
| | | | - List Item Discount on L Items 25.00/25.00% (S\$) | 2,426.58 | 106.40 |
| | | | Total Parts (S\$) | 7,659.72 | 364.20 |

Report was unsubmitted during this print-out.

11/9/21, 9:44 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|---|---------------|------------|--------|
| Lab | our Items | | | |
| 1 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR | New | 380.00 | 0.00 |
| 2 | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME. | New | 2,200.00 | 150.00 |
| 3 | TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| 4 | TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 180.00 | 0.00 |
| 5 | TO REMOVE AND REFIT ELECTRICAL WIRING ,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR | New | 480.00 | 0.00 |
| 6 | TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. | New | 480.00 | 0.00 |
| 7 | TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT ,VACUUM AND CHARGE-IN-GAS | New | 380.00 | 0.00 |
| 8 | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR | New | 380.00 | 0.00 |
| 9 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 10 | TO RUST PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS | New | 250.00 | 0.00 |
| 11 | TOWING FEES | New | 150.00 | 0.00 |
| 12 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 2,200.00 | 220.00 |
| 13 | TO REINSTALL REAR BUMPER PARKING SENSOR | New | 170.00 | 0.00 |
| 14 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 0.00 |
| 15 | TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| 16 | TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING | New | 220.00 | 0.00 |
| 17 | TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR | New | 170.00 | 0.00 |
| 18 | TO LIFT -UP /OUT ENGINE WITH GEAR BOX AND REFIT | New | 440.00 | 0.00 |
| 19 | TO REMOVE AND REFIT RADIATOR SUPPORT CROSS -MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR | New | 380.00 | 0.00 |
| 20 | TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS | New | 380.00 | 0.00 |
| | Gross Labor | ur Cost (S\$) | 9,990.00 | 370.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >