

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003559/KGA3Q2**Date:** 12/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070165132
Claimant Vehicle No :	GY8262T	Insured Vehicle No :	SFQ3533Z
Date of Loss:	12/03/2021	Nature of Claim:	TP
		Claim No:	0825282921SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY8262T	Engine No:	Z17DTH01333677
Make & Model:	OPEL COMBO, 1.7 D AZ (M)	Chassis No:	W0L0XCF2553063623
Reg. Date:	22/08/2005 (Man. Year: 2005)	Odometer:	235495 km
Colour:	Blue		
Engine Capacity:	1686 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,750.70	2,662.70	88.00	3.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,530.00	350.00	18.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,630.70	4,192.70	438.00	9.46
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	4,630.70	3,350.00	1,280.70	27.66
+ GST 7.00/7.00% (S\$)	324.15	234.50	89.65	27.66
Nett Amount (S\$)	4,954.85	3,584.50	1,370.35	27.66
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,946.50		

INSPECTION

Date of Assignment:	18/03/2021	
Date Inspected:	22/03/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	850.00 FL	*850.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	420.00 FL	*420.00 FL
3	2		*REAR BUMPER TOP SPONGE	Cracked	170.00 FL	*170.00 FL
4	1		*REAR END PANEL OUTER	Bent	490.00 FL	*490.00 FL
5	1		*REAR END PANEL INNER TOP GARNISH	Dented	175.00 FL	*175.00 FL
6	2		*REAR END PANEL INNER ATTACHMENTS	Bent	220.00 FL	*220.00 FL
7	1		*LH TAILGATE INNER LOCK	Dented	190.00 FL	*190.00 FL
8	1		*TAILGATE INNER RUBBER (50%)	Distorted / Dented	198.00 FS	*110.00 FS
9	1		*TAILGATE LH EMBLEM (OPEL)	Necessary	88.00 FL	*88.00 FL
10	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
11	1		*STICKER -70KM/H	Necessary	10.00 FS	*10.00 FS
					Sub Total (\$\$)	3,011.00 2,923.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	260.30 260.30
					Total Parts (\$\$)	2,750.70 2,662.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY ,REAR GARNISH,CARPET ,TO STRAIGHTEN ,CUT ,WELD &RENEW REAR END PANEL OUTER ,KNOCK OUT ,REPAIR REAR FLOOR BOARD ,LH TAILGATE & REALIGN THE SAME	New	900.00	700.00
2	PUTTY & RESPRAY ON REAR END PANEL ,REAR FLOOR BOARD PANEL ,REAR BUMPER ,REAR BOTH SIDE PANELS ,LH TAILGATE	New	950.00	800.00
3	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,880.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >