

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003561/KGS3Q2
Date: 11/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900153124
Claimant Vehicle No :	SFR7140S	Insured Vehicle No :	SKW1771A
Date of Loss:	16/03/2021	Nature of Claim:	TP
		Claim No:	6428383942SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFR7140S		
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Engine No:	HIDDEN
Reg. Date:	01/02/2005 (Man. Year: 2005)	Chassis No:	MR053BK3106008745
Colour:	Metallic Black	Odometer:	152141 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Dayton 6 mm	Rear Left Side:	Dayton 4 mm
Front Right Side:	Dayton 6 mm	Rear Right Side:	Dayton 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,653.44	2,799.87	853.57	23.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,230.00	270.00	18.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,153.44	4,029.87	1,123.57	21.80
Approved Total (Overridden) (S\$)		3,200.00		

(S\$)	5,153.44	3,200.00	1,953.44	37.91
+ GST 7.00/7.00% (S\$)	360.74	224.00	136.74	37.91
Nett Amount (S\$)	5,514.18	3,424.00	2,090.18	37.91
+ Car Rental (3.0 x S\$150.00/day + 7.00% GST) (S\$)		481.50		
Nett Liability (S\$)		3,905.50		

INSPECTION

Date of Assignment: 18/03/2021

Date Inspected: 22/03/2021

Inspected At:

BCC Automotive Pte Ltd (Sin Ming)
 Blk 1 Sin Ming Industrial Estate, Sector C #01-101
 Singapore 575636

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BOOT LID	Bent	1,060.35 FL	*1,145.20 FL	
2	1		*REAR BOOT LOCK	Repair	155.00 FL	*- FL	
3	1		*REAR BOOT CATCH	Repair	80.00 FL	*- FL	
4	1		*REAR BOOT GARNISH (CHROME)	Serviceable	155.00 FL	*- FL	
5	1		*REAR BUMPER	Buckled	794.00 FL	*622.10 FL	
6	1		*REAR BUMPER LH PROTECTOR W/CHROME	Necessary	95.00 FL	*95.00 FL	
7	1		*REAR BUMPER RETAINER LH	Distorted	60.00 FL	*60.00 FL	
8	1		*REAR BUMPER RETAINER RH	Serviceable	60.00 FL	*- FL	
9	1		*REAR LH OUTER LAMP	Cracked	953.60 FL	*675.20 FL	
10	1		*TOYOTA EMBLEM	Necessary	60.00 FL	*60.00 FL	
11	1		*2.0 EMBLEM	Necessary	55.00 FL	*55.00 FL	
12	1		*CAMRY EMBLEM	Necessary	69.00 FL	*69.00 FL	
13	1		*REAR NUMBER PLATE W/FRAME	Dented	50.00 FS	*45.00 FS	
14	1		*REAR END PANEL	Bent	834.30 FL	*625.00 FL	
15	1		*REVERSE SENSOR	Torn	280.00 FS	*200.00 FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$\$)	4,761.25	3,651.50
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,107.81	851.63
					Total Parts (\$\$)	3,653.44	2,799.87

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SPRAY THE REAR PANEL & THE REAR LH FENDER	New	300.00	180.00
2	TO PANEL BEAT THE AFFECTED AREA	New	500.00	450.00
3	TO SPRAY PAINT ON THE AFFECTED AREA	New	700.00	600.00
Gross Labour Cost (\$\$)			1,500.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >