

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21003562/ARS3Q2
Date: 30/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700067840
Claimant Vehicle No :	GBE5527P	Insured Vehicle No :	SLT1438S
Date of Loss:	15/03/2021	Nature of Claim:	TP
		Claim No:	9774698396SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE5527P		
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No:	1KD2569220
Reg. Date:	29/12/2015 (Man. Year: 2015)	Chassis No:	KDY2318022428
Colour:	Blue	Odometer:	308207 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	165 R13C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,615.19	2,672.50	1,942.69	42.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	1,240.00	580.00	31.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,435.19	3,912.50	2,522.69	39.20
Approved Total (Overridden) (S\$)		3,100.00		

Nett Amount (S\$)	6,435.19	3,100.00	3,335.19	51.83
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,607.45		

INSPECTION

Date of Assignment: 19/03/2021

Date Inspected: 19/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Premium Carz Services Pte Ltd (HQ)
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	498.50 FL	*498.50 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	165.00 FL	*- FL
3	1		*FRONT CORNEL PANEL RH	Repair	279.30 FL	*- FL
4	1		*FRONT GRILLE	Cracked	501.50 FL	*501.50 FL
5	10		*FRONT GRILLE CLIP	Necessary	50.00 FL	*20.00 FL
6	1		*FRONT GRILLE RUBBER SEAL	Not Necessary	128.00 FL	*- FL
7	1		*FRONT GRILLE TOYOTA LOGO	Necessary	61.50 FL	*61.50 FL
8	1		*HEADLAMP RH	Cracked	1,140.00 FL	*726.00 FL
9	1		*HEADLAMP LOWER SEAL RH	Not Necessary	75.00 FL	*- FL
10	1		*FRONT DOOR RH	Dented	1,550.00 FL	*1,349.00 FL
11	1		*FRONT DOOR LOWER RUBBER RH	Not Necessary	85.50 FL	*- FL
12	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	195.60 FL	*- FL
13	1		*FRONT DOOR CHANEL RH	Not Necessary	201.75 FL	*- FL
14	1		*FRONT DOOR OUTER MOULDING RH	Not Necessary	109.30 FL	*- FL
15	1		*FRONT DOOR HINGES RH	Lower Bent	179.00 FL	*89.50 FL
16	1		*FRONT DOOR CHECK RH	Not Necessary	196.30 FL	*- FL
17	1		*FRONT DOOR STEP PANEL RH	Not Necessary	300.00 FL	*- FL
18	1		*SET COMPANY REGISTRATION STICKER	Necessary	80.00 FS	*30.00 FS
19	1		*COMPANY STICKER	Necessary	100.00 FS	*60.00 FS
20	1		*FOG LAMP RH (NPA)	Not Necessary	0.00 FS	*- FS
21	1		*FRONT DOOR SIGNAL LAMP RH	Cut	148.00 FS	*148.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,044.25	3,484.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,429.06	811.50
Total Parts (\$\$)	4,615.19	2,672.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	60.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	800.00	500.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREA	New	800.00	600.00
4	TO SPRAY ANTI-RUST UNDERCOAT	New	60.00	30.00
5	TO REMOVE AND REFIT FRONT DOOR GLASS RH	New	100.00	80.00
Gross Labour Cost (\$)			1,820.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >