

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21003572/GQD3E2

Date: 04/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100377656		
Claimant Vehicle No :	SLW571E	Insured Vehicle No :	SFQ6160X		
Date of Loss:	15/03/2021	Nature of Claim:	TP	Claim No:	9129108471SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW571E	Engine No:	FB20YB44220
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Chassis No:	JF1SJ5KC5JG100376
Reg. Date:	11/12/2017 (Man. Year: 2017)	Odometer:	63651 km
Colour:	Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	17/03/2021		
Date Inspected:	18/03/2021	Inspected At:	Precise Auto Services (HQ) NO.1 KAKI BUKIT AVE 6 #02-34/36 Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$78,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	0.00 F	*- F
2	1		*REAR BUMPER TOW COVER	Distorted	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Broken	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Cracked	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
6	1		*REAR BUMPER SPONGE	* Check	0.00 F	*- F
7	1		*REAR BUMPER STEP GUARD	Distorted	0.00 F	*- F
8	1		*REAR BUMPER REFLECTOR LH	Cracked	0.00 F	*- F
9	1		*REAR BUMPER LOWER SPOILER	Cracked	0.00 F	*- F
10	1		*REVERSE SENSOR	Cut	0.00 F	*- F
11	1		*REAR END PANEL	Repair	0.00 F	*- F
12	1		*REAR END PANEL TOP GARNISH	* Check	0.00 F	*- F
13	1		*REAR LH TAILLAMP	* Check	0.00 F	*- F
14	1		*REAR RH TAILLAMP	* Check	0.00 F	*- F
15	1		*TAILGATE	Dented	0.00 F	*- F
16	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
17	1		*TAILGATE MOULDING	Bent	0.00 F	*- F
18	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
19	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
20	1		*TAILGATE LOCK	Buckled	0.00 F	*- F
21	1		*TAILGATE RUBBER	Dented	0.00 F	*- F
22	1		*TAILGATE INNER BOARD	* Check	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >