



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2108081

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 20/11/2021  
Reference CC4/FCI21003573/Kra3q2  
Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. FBQ 1221J  
Insured Veh. XD 9654Z  
Claim No. D21000727MFCV/1  
Policy No. D-20095634MFCV  
Accident Date 04/03/2021  
Inspection Date 19/03/2021

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>250.00</b>
<b>GST (7%)</b>	<b>17.50</b>
<b>Grand Total</b>	<b>267.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21003573/Kra3q2	
			Date: 20/11/2021	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	XD 9654Z	Veh. Inspected	FBQ 1221J
	Policy No.	D-20095634MFCV	Coverage (\$)	0.00
	Claim No.	D21000727MFCV/1	Excess (\$)	0.00
	Assign From	ESTHER	Assign Date	18/03/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	YAMAHA FZS	c.c	149
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	ME1RG44F4K0022236	Colour	BLUE/ GREY
	Odometer	10459 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	100/80 R17	MRF	7 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	140/60 R17	MRF	7 mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/03/2021	Inspection Date	19/03/2021
	Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 1221J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BOX BRACKET	TO REPAIR SEE LABOUR	95.00	-
1	REAR BOX TRAY	SERVICEABLE	115.00	-
2	REAR MUD GUARD @\$48.00	SERVICEABLE	96.00	-
1	REAR MUD GUARD BRACKET	TO REPAIR SEE LABOUR	98.00	-
1	EXHAUST	TO REPAIR SEE LABOUR	498.00	-
1	EXHAUST GARNISH (BLACK)	DENTED / CUT	32.00	32.00
1	EXHAUST GARNISH (SILVER)	DENTED / CUT	48.00	48.00
1	HANDLE BAR	SERVICEABLE	26.00	-
1	BALANCER	DENTED	18.00	18.00
1	GRIP	DENTED	25.00	25.00
1	REAR VIEW MIRROR	DENTED	95.00	95.00
1	BRAKE LEVER	DENTED	182.00	182.00
1	STEERING CONE	SERVICEABLE	98.00	-
1	PETROL TANK GARNISH RH	DENTED / CUT	188.00	188.00
1	PETROL TANK GARNISH CHROME	SERVICEABLE	65.00	-
1	RIDER STAND RH	DISTORTED	22.00	22.00
1	REAR BRAKE FOOT LEVER	BENT	34.00	34.00
1	BELLY PAN GARNISH	SERVICEABLE	85.00	-
1	FRONT MUD GUARD	SERVICEABLE	65.00	-
1	FRONT FORK	SERVICEABLE	525.00	-
2	FRONT WHEEL BEARING @\$10.00	NOT NECESSARY	20.00	-
1	RH FRONT INDICATOR	SERVICEABLE	95.00	-
1	FRONT RADIATOR GUARD RH	SERVICEABLE	38.00	-
1	LH RIDER STAND	DISTORTED	18.00	18.00
	LESS 10% DISCOUNT		-258.10	-66.20
			2,322.90	595.80
1	REAR BOX (SN)	DENTED / CUT	485.00	250.00

Report Ref No. CC4/FCI21003573/Kra3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-48.50	-
			436.50	250.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	PETROL TANK GARNISH STICKER (SN)	NECESSARY	55.00	55.00
			55.00	55.00
	<b><u>LABOUR</u></b>			
	REALIGN AND PRESS FRONT FORK ,REAR ALIGN REAR SWING ARM.INCLUSIVE OF THE REPAIR OF REAR BOX BRACKET ,REAR MUD GUARD BRACKET AND EXHAUST .		450.00	300.00
	TOWING CHARGE.		50.00	30.00
			500.00	330.00
<b>GRAND TOTAL</b>			<b>3,314.40</b>	<b>1,230.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,000.00</b>

Report Ref No. CC4/FCI21003573/Kra3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. FBQ 1221J

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. FBQ 1221J

### RE-INSPECTION

