

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21003587/R1vf3e2
	8 SHENTON WAY TOWERSINGAPOR	-	Date	e: 01/04/2021
	ATTN : YU DOMIN	IC YISHAN	Cod	e: ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SHB 4079S	Veh. Inspected	SJC 3679M
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M0356U	Excess (\$)	0.00
	Assign From	YU DOMINIC YISHAN	Assign Date	18/03/2021
2.	Vehicle Particulars & Condition			
	Make & Model	TOYOTA ESTIMA AERAS 2.4A	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	ACR500057496	Colour	WHITE
	Odometer	219264 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55Z R17	KAPSEN	6 mm
	L/H Front Tyre	215/55Z R17	KAPSEN	6 mm
	R/H Rear Tyre	215/55Z R17	KAPSEN	6 mm
	L/H Rear Tyre	215/55Z R17	KAPSEN	6 mm
4.	Description of Damages			
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA		
5.	General Information			
	Accident Date	11/03/2021	Inspect Date / Time	19/03/2021 (04:35 PM)
	Survey held at	Block 40 Toh Guan Road East #0	01-67	
	Repairer	MASTER CAR SPRAY SERVICE		
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b.	b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			

Report Ref No. CS3/ASM21003587/R1vf3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser