

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21003590/R1TF3Q2**Date:** 14/04/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900098239
Claimant Vehicle No :	FBB3982L	Insured Vehicle No :	SML3519J
Date of Loss:	13/03/2021	Nature of Claim:	TP
		Claim No:	0929966483SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBB3982L	Engine No:	5YP718051
Make & Model:	YAMAHA T135, 135cc	Chassis No:	5YP718051
Reg. Date:	23/03/2007 (Man. Year: 2007)	Odometer:	36706 km
Colour:	Multi-colour		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/19-17	Rear Tyre Size:	80/19-17
Front Left Side:	Maxxis 3 mm	Rear Left Side:	Maxxis 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	19/03/2021	Hua Chin (2000) Trading Motor Service Centre (HQ)
Date Inspected:	19/03/2021 Inspected At:	50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING
Estimated Period of Repair:	5.0 days	Singapore 659578

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Scratched	0.00 F	*- F
3	1		*FRONT BRAKE DISC	Scratched	0.00 F	*- F
4	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
5	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
6	1		*FRONT HEADLAMP	Scratched	0.00 F	*- F
7	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
8	1		*FRONT WING MIRROR	Scratched	0.00 F	*- F
9	1		*METER CASING	Cracked	0.00 F	*- F
10	1		*HANDLE BAR	Bent	0.00 F	*- F
11	1		*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F
12	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
13	1		*FAIRING SHIELD INNER	Cracked	0.00 F	*- F
14	1		*REAR FAIRING	Scratched	0.00 F	*- F
15	1		*FOOT BRAKE	Bent	0.00 F	*- F
16	1		*FRONT FOOT REST	Bent	0.00 F	*- F
17	1		*EXHAUST MUFFLER ASSY	Bent	0.00 F	*- F
18	1		*REAR BOX	Scratched	0.00 F	*- F
19	1		*BASKET	Scratched	0.00 F	*- F
					Total Parts (S\$)	0.00
						0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >