

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21003597/URS3Q2
Date: 25/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700077924
Claimant Vehicle No :	GBL137C	Insured Vehicle No :	SLU7177A
Date of Loss:	17/03/2021	Nature of Claim:	TP
		Claim No:	4838842551SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL137C		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KDB071582
Reg. Date:	24/02/2021 (Man. Year: 2021)	Chassis No:	JTFAT35YX0K216428
Colour:	Silver	Odometer:	24587 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,344.00	0.00	1,344.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	520.00	330.00	38.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,194.00	520.00	1,674.00	76.30
+ GST 7.00/7.00% (S\$)	153.58	36.40	117.18	76.30

Nett Amount (S\$)	2,347.58	556.40	1,791.18	76.30
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		858.40		

INSPECTION

Date of Assignment: 30/08/2021

Date Inspected: 30/08/2021

Estimated Period of Repair: 2.0 days

Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR END PANEL	Repair	385.70 FL	*- FL
2	1		*O/S TAILLAMP	Serviceable	307.80 FL	*- FL
3	1		*O/S TAILLAMP HOLDER	Not Necessary	99.80 FL	*- FL
4	1		*O/S REAR CARGO REAR DOOR (DENTED)	Not Consistent With The Impact	998.70 FL	*- FL
					Sub Total (\$\$)	1,792.00 0.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	448.00 0.00
					Total Parts (\$\$)	1,344.00 0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	20.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	500.00	300.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	300.00	200.00
Gross Labour Cost (\$\$)			850.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >