

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003599/DPS3Q2
Date: 27/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993670
Claimant Vehicle No :	SJV8726C	Insured Vehicle No :	SKU7123S
Date of Loss:	18/03/2021	Nature of Claim:	TP
		Claim No:	3581810966SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV8726C		
Make & Model:	HONDA AIRWAVE, 1.5 (A)	Engine No:	L15A5160611
Reg. Date:	10/02/2010 (Man. Year: 2008)	Chassis No:	GJ11208976
Colour:	Silver	Odometer:	126906 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,056.97	2,972.96	17,084.01	85.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,570.00	1,790.00	4,780.00	72.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,626.97	4,762.96	21,864.01	82.11
Approved Total (Overridden) (S\$)		3,800.00		

(S\$)	26,626.97	3,800.00	22,826.97	85.73
+ GST 7.00/7.00% (S\$)	1,863.89	266.00	1,597.89	85.73
Nett Amount (S\$)	28,490.86	4,066.00	24,424.86	85.73
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		4,637.45		
Global Sum Settlement (S\$)		4,630.00		

INSPECTION

Date of Assignment: 19/03/2021

Date Inspected: 22/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
 Singapore 568047

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,780.50 FL	*1,141.30 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	329.38 FL	*112.50 FL
3	1		*TAILGATE AIRWAVE EMBLEM	Necessary	58.50 FL	*58.50 FL
4	1		*TAILGATE HONDA EMBLEM	Necessary	50.20 FL	*50.20 FL
5	1		*TAILGATE CENTER CHROME	Not Necessary	498.92 FL	*- FL
6	1		*TAILGATE CENTER GARNISH	Not Necessary	651.52 FL	*- FL
7	2		*TAILGATE LAMP L+R	Not Necessary	890.60 FL	*- FL
8	2		*TAILGATE HINGE L+R	Not Necessary	213.16 FL	*- FL
9	2		*TAILGATE NO.PLATE LAMP L+R	Not Necessary	105.60 FL	*- FL
10	1		*TAILGATE NO.PLATE LAMP TOP GARNISH	Not Necessary	460.90 FL	*- FL
11	1		*TAILGATE INNER TRIM BOARD	Not Necessary	748.30 FL	*- FL
12	1		*REAR BUMPER	Distorted / Cracked	1,378.50 FL	*945.20 FL
13	1		*REAR BUMPER SPONGE	No such part	310.90 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	90.00 FL	*- FL
15	1		*REAR BUMPER BEAM	Bent	159.20 FL	*159.20 FL
16	1		*REAR END PANEL	Dented	808.72 FL	*508.70 FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	238.54 FL	*- FL
18	1		*SPARE WHEEL PANEL	Not Necessary	1,526.82 FL	*- FL
19	2		*SPARE WHEEL QUARTER PANEL L+R	Not Necessary	1,960.40 FL	*- FL
20	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	620.39 FL	*- FL
21	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	498.70 FL	*- FL
22	2		*REAR FENDER L+R	Not Necessary	2,700.58 FL	*- FL
23	2		*REAR FENDER INNER TRIM L+R	Not Necessary	1,125.64 FL	*- FL
24	2		*REAR FENDER QUARTER GLASS MOULDING L+R	Not Necessary	1,698.58 FL	*- FL
25	1		*TAIL LAMP L+R	O/SNot Necessary/N/SMtgCracked	993.70 FL	*390.60 FL
26	2		*TAIL LAMP PANEL L+R	Not Necessary	379.46 FL	*- FL
27	1		*REAR EXHAUST PIPE	Not Necessary	2,198.00 FL	*- FL
28	1		*REAR EXHAUST MOUNTING	Not Necessary	98.00 FL	*- FL
29	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	210.00 FL	*- FL
30	1		*REAR NUMBER PLATE & CASING	Not Necessary	100.00 FS	*- FS
31	1		*SET REAR REVERSE SENSOR	Damaged / Distorted	300.00 FS	*220.00 FS
32	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
33	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
37	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	120.00 FS	*- FS
38	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
39	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
41	1		*TAILGATE CENTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*TAILGATE CENTER CHROME CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
45	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	24,613.71
					- List Item Discount on L Items 20.00/20.00% (\$\$)	4,556.74
					Total Parts (\$\$)	20,056.97

2,972.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	700.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	700.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
6	TO RNR REVERSE SENSOR	New	100.00	0.00
7	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	300.00	0.00
8	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	400.00	120.00
9	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	80.00
10	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
11	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
12	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
13	TO RNR REVERSE SENSOR TO FACILITATE REPAIRS	New	120.00	40.00
Gross Labour Cost (\$\$)			6,570.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >