

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21003602/URA3Q2
Date: 05/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900015356
Claimant Vehicle No :	SMP6368L	Insured Vehicle No :	SME4370A
Date of Loss:	18/03/2021	Nature of Claim:	TP
		Claim No:	0952090786SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP6368L	Engine No:	G4FGKU153662
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMKU916757
Reg. Date:	07/10/2019 (Man. Year: 2019)	Odometer:	52482 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 8 mm	Rear Left Side:	Kumho 8 mm
Front Right Side:	Kumho 8 mm	Rear Right Side:	Kumho 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,223.60	1,278.56	1,945.04	60.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,000.00	1,540.00	60.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,763.60	2,278.56	3,485.04	60.47
+ GST 7.00/7.00% (S\$)	403.45	159.50	243.95	60.47

Nett Amount (S\$)	6,167.05	2,438.06	3,728.99	60.47
+ Car Rental (3.5 x S\$100.00/day + 7.00% GST) (S\$)		374.50		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,814.56		

INSPECTION

Date of Assignment: 19/03/2021

Date Inspected: 19/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID WEATHERSTRIP	Not Necessary	251.00 FL	*- FL
2	1		*BOOTLID S BADGE	Not Necessary	59.00 FL	*- FL
3	1		*BOOTLID CENTRE EMBLEM BADGE	Not Necessary	54.00 FL	*- FL
4	1		*BOOTLID AVENTE BADGE	Not Necessary	51.00 FL	*- FL
5	1		*BOOTLID DRAIN PLUG	Not Necessary	36.00 FL	*- FL
6	1		*BOOTLID LOCK TOP	Not Necessary	116.00 FL	*- FL
7	1		*BOOTLID LAMP O/S	Not Necessary	286.00 FL	*- FL
8	1		*REAR LAMP O/S	Not Necessary	307.00 FL	*- FL
9	1		*REAR BUMPER	Dented	659.00 FL	*598.20 FL
10	1		*REAR BUMPER LOWER	Dented	350.00 FL	*350.00 FL
11	2		*REAR BUMPER SIDE RETAINER	Not Necessary	88.00 FL	*- FL
12	2		*REAR BUMPER REFLECTOR	Serviceable	82.00 FL	*- FL
13	1		*REAR BUMPER REINFORCEMENT	Cracked	350.00 FL	*350.00 FL
14	1		*REAR BUMPER LOWER SPLASH COVER	Not Necessary	82.00 FL	*- FL
15	1		*REAR BUMPER LOWER SPLASH COVER CLIPS	Not Necessary	36.00 FL	*- FL
16	1		*REAR BUMPER SIDE BRACKET	Not Necessary	176.00 FL	*- FL
17	1		*REAR BUMPER TOP BRACKET	Not Necessary	50.00 FL	*- FL
18	1		*REAR END PANEL	Repair	379.00 FL	*- FL
19	1		*REAR END PANEL INNER TRIM	Not Necessary	59.00 FL	*- FL
20	6		*REAR END PANEL INNER TRIM CLIPS	Not Necessary	21.00 FL	*- FL
21	1		*REAR LICENCE PLATE	Scratched	80.00 FS	*40.00 FS
22	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,922.00	1,538.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	698.40	259.64
Total Parts (\$\$)	3,223.60	1,278.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	100.00	0.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	180.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	100.00	60.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	150.00	40.00
6	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	950.00	380.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,000.00	500.00
Gross Labour Cost (S\$)			2,540.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >