

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21003609/AGA3Q2**Date:** 14/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000326_01

Claimant Vehicle No : SMM9208L **Insured Vehicle No :** SMJ1734C

Date of Loss: 16/03/2021 Nature of Claim: TP Claim No: MFL2021D0001171

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM9208L**
 Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR2B88994
 Reg. Date: 18/07/2019 (Man. Year: 2018) Chassis No: ZYX102149252
 Colour: Black Odometer: 141177 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: Windforce 6 mm Rear Left Side: Windforce 6 mm
 Front Right Side: Windforce 6 mm Rear Right Side: Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,127.37	4,193.52	933.85	18.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	2,030.00	1,910.00	48.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,067.37	6,223.52	2,843.85	31.36
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	9,067.37	4,900.00	4,167.37	45.96
+ GST 7.00/7.00% (S\$)	634.72	343.00	291.72	45.96
Nett Amount (S\$)	9,702.09	5,243.00	4,459.09	45.96
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,810.45		

INSPECTION

Date of Assignment: 17/03/2021

Date Inspected: 17/03/2021 Inspected At:

Mg Solution Pte Ltd - Kaki Bukit (HQ)
25 Kaki Bukit Road 4 #04-01
Singapore 41800

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Feb 2022)

Parts: M1-SUV TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMM9208L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,366.90 FL	*1,204.00 FL
2	1		*BOOT LID LOGO	Not Necessary	80.00 FL	*- FL
3	1		*BOOT LID EMBLEM CH-R	Not Necessary	72.00 FL	*- FL
4	1		*BOOT LID EMBLEM HYBRID SYNERGY DRIVE	Not Necessary	95.30 FL	*- FL
5	1		*BOOTLID WEATHERSTRIP	Cut	240.30 FL	*240.30 FL
6	1		*BOOTLID LOCK	Damaged	320.00 FL	*320.00 FL
7	1		*BOOTLID DETECTOR	Not Necessary	180.30 FL	*- FL
8	1		*BOOTLID WINDSCREEN MOULDING	Necessary	211.30 FL	*211.30 FL
9	1		*REAR BUMPER	Deformed	850.00 FL	*850.00 FL
10	1		*REAR BUMPER LOWER LID	Deformed	580.00 FL	*398.00 FL
11	2		*REAR BUMPER SIDE RETAINER	Necessary	124.80 FL	*124.80 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	555.00 FL	*382.00 FL
13	1		*REAR BUMPER TOWING COVER	Missing	66.50 FL	*66.50 FL
14	2		*REAR BUMPER REFLECTOR HOUSING	Cut	364.60 FL	*364.60 FL
15	1		*REAR END PANEL	Dented	860.30 FL	*694.00 FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	189.20 FL	*189.20 FL
17	1		*REAR NUMBER PLATE	Dented	50.00 FS	*50.00 FS
18	1		*BOOTLID WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
19	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
20	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
21	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
22	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,666.50	5,454.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,539.13	1,261.18
Total Parts (\$\$)	5,127.37	4,193.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	160.00	30.00
5	UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	120.00	50.00
8	TRANSFER BOOT LID MECHANISM	New	80.00	60.00
9	TO REMOVE AND REFIX REAR WINDSCREEN	New	160.00	120.00
Gross Labour Cost (S\$)			3,940.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >