



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 3567U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR LH DOOR	BENT	825.00	705.60
1	REAR LH DOOR STICKER @ PILLAR FRONT	SERVICEABLE	65.00	-
1	REAR LH DOOR OUTER GARNISH MOULDING @ WINDOW GLASS	SERVICEABLE	75.00	-
1	REAR LH DOOR RUBBER @ REAR	SERVICEABLE	175.00	-
1	ROCKER PANEL	TO REPAIR SEE LABOUR	280.00	-
	LESS 25% DISCOUNT		-355.00	-176.40
			1,065.00	529.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR LH DOOR INNER COMPARTMENT CLIPS (SN)	NOT NECESSARY	70.00	-
			70.00	-
	<b><u>LABOUR</u></b>			
	SPRAY PAINTING ON ALL AFFECTED AREA.		400.00	400.00
	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF ROCKER PANEL.		600.00	400.00
	TO APPLY ANTI RUST TREATMENT.		100.00	30.00
	TO CHECK WIRING SYSTEM & LIGHT.		100.00	20.00
	TO REMOVE/REFIX REAR LH WINDOW GLASS,MECHANISM & ETC TO NEW DOOR.		150.00	60.00
			1,350.00	910.00
	<b>GRAND TOTAL</b>		<b>2,485.00</b>	<b>1,439.20</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,100.00</b>

Report Ref No. CS/AGI21003610/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.