

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003613/KPA3Q2
Date: 17/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900015938
Claimant Vehicle No :	SLA6309Z	Insured Vehicle No :	SMH9837Y
Date of Loss:	17/03/2021	Nature of Claim:	TP
		Claim No:	2506458219SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA6309Z		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Engine No:	1ZRY269866
Reg. Date:	09/03/2016 (Man. Year: 2016)	Chassis No:	MR053REH104548224
Colour:	Metallic Silver	Odometer:	114690 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,484.52	2,484.52	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	1,120.00	30.00	2.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,634.52	3,604.52	30.00	0.83
Approved Total (Overridden) (S\$)		2,850.00		

(S\$)	3,634.52	2,850.00	784.52	21.59
+ GST 7.00/7.00% (S\$)	254.42	199.50	54.92	21.59
Nett Amount (S\$)	3,888.94	3,049.50	839.44	21.59
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 19/03/2021

Date Inspected: 24/03/2021

Inspected At:

Ah Lim Motor Company (Sin Ming)
 176 Sin Ming Drive #05-12, Sin Ming AutoCare
 Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Bent	1,248.50 FL	*1,248.50 FL
2	1		*REAR DOOR LH TAPE	Necessary	53.50 FL	*53.50 FL
3	1		*RR ALLOY RIM LH	Dented	2,010.70 FL	*2,010.70 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	3,312.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	828.18
					Total Parts (\$\$)	2,484.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE AND INSTALL REAR DOOR LH ,TRANFER DOOR INNER PARTS ,GLASS AND WIRING HARNESS	New	80.00	60.00
2	TO CARRYING OUT WHEEL ALIGNMENT	New	70.00	60.00
3	TO KNOCK AND REPAIR REAR FENDER LH AND REFIT LISTED LISTED PARTS BACK SAME	New	400.00	400.00
4	TO SPRAY REAR DOOR LH REAR FENDER LH AND REAR BUMPER	New	600.00	600.00
Gross Labour Cost (S\$)			1,150.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >