

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21003614/R1S3Q2
Date: 11/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070166778
Claimant Vehicle No :	SKR5607S	Insured Vehicle No :	SMW6368A
Date of Loss:	18/03/2021	Nature of Claim:	TP
		Claim No:	8311006567SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR5607S	Engine No:	CXS228823
Make & Model:	VOLKSWAGEN GOLF, 1.4 A7 TSI (A)	Chassis No:	WVWZZZAUZFW139050
Reg. Date:	13/02/2015 (Man. Year: 2014)	Odometer:	28903 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R17	Rear Tyre Size:	225/40 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,732.95	1,553.45	1,179.50	43.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	2,400.00	3,280.00	57.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,412.95	3,953.45	4,459.50	53.01
+ GST 7.00/7.00% (S\$)	588.91	276.74	312.17	53.01

Nett Amount (S\$)	9,001.86	4,230.19	4,771.67	53.01
		+ Loss of Use (3.0 x S\$60.00/day) (S\$)	180.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	4,412.19	

INSPECTION

Date of Assignment: 19/03/2021

Date Inspected: 23/03/2021

Estimated Period of Repair: 3.0 days

Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Adjuster: MOHD RASUL**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,251.35 FS	*1,251.35 FS
2	1		*BUMPER (REINFORCEMENT)	Serviceable	626.36 FS	*- FS
3	1		*ATTACHMENT STRIP	Serviceable	67.89 FS	*- FS
4	1		*REAR DIFFUSOR SATIN BLACK	Serviceable	328.37 FS	*- FS
5	1		*GUIDE PIECE (BUMPER BRACKET LH)	Serviceable	39.22 FS	*- FS
6	1		*GUIDE PIECE (BUMPER BRACKET RH)	Serviceable	39.22 FS	*- FS
7	1		*GUIDE PIECE (TAILLAMP BRACKET LH)	Serviceable	39.22 FS	*- FS
8	1		*GUIDE PIECE (TAILLAMP BRACKET RH)	Serviceable	39.22 FS	*- FS
9	1		*SET SENSOR BRACKETS PRI	Necessary	22.34 FS	*22.34 FS
10	1		*SENSOR BRACKET	Necessary	14.51 FS	*14.51 FS
11	1		*SENSOR BRACKET	Necessary	14.51 FS	*14.51 FS
12	1		*SENSOR BRACKET	Necessary	14.51 FS	*14.51 FS
13	1		*SENSOR BRACKET	Necessary	14.51 FS	*14.51 FS
14	1		*BONDING AGENT FOR PLASTIC	Necessary	62.81 FS	*62.81 FS
15	1		*2K-PLASTIC ADHESIVE	Necessary	78.91 FS	*78.91 FS
16	1		*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)
2,732.95
1,553.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINTING	New	2,400.00	800.00
Gross Labour Cost (\$)			5,680.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >